Mauna Loa Solar Observatory Observer's Log _____ Sun Jan 11 17:16:11 GMT 1998 Year: 98 Doy: 011 Observer: koon WEATHER COMMENT: Sun Jan 11 17:17:01 GMT 1998 Thin cirrostratus, wind=10 mph from the SW, temp=40 F. Sun Jan 11 17:37:32 GMT 1998 CHIP Startup--Initializing new tape Sun Jan 11 17:39:27 GMT 1998 CHIP CHIP Start Patrol PSPT COMMENT: Sun Jan 11 17:40:15 GMT 1998 Will wait for clouds to clear before starting. MKIII COMMENT: Sun Jan 11 17:40:34 GMT 1998 Will wait for clouds to clear before starting. Sun Jan 11 17:41:02 GMT 1998 PICS Start Patrol PICS COMMENT: Sun Jan 11 17:42:26 GMT 1998 Stalled with Program: init, did Kill/Run to fix. Sun Jan 11 17:43:20 GMT 1998 PICS Start Patrol Sun Jan 11 18:00:14 GMT 1998 PICS Flat Sun Jan 11 18:01:04 GMT 1998 CHIP Bias Sun Jan 11 18:01:46 GMT 1998 PICS End Flat Sun Jan 11 18:02:03 GMT 1998 End Bias CHIP Sun Jan 11 18:02:10 GMT 1998 CHIP Water Sun Jan 11 18:02:52 GMT 1998 CHIP End Water Sun Jan 11 19:00:19 GMT 1998 PICS Flat Sun Jan 11 19:01:08 GMT 1998 CHIP Bias Sun Jan 11 19:01:42 GMT 1998 End Flat PICS Sun Jan 11 19:02:20 GMT 1998 End Bias CHIP Sun Jan 11 19:02:27 GMT 1998 CHIP Water Sun Jan 11 19:03:09 GMT 1998 CHIP End Water Sun Jan 11 20:00:21 GMT 1998 PICS Flat Sun Jan 11 20:01:14 GMT 1998 CHIP Gain Sun Jan 11 20:01:49 GMT 1998 PICS End Flat Sun Jan 11 20:07:15 GMT 1998 CHIP End Gain Sun Jan 11 20:07:22 GMT 1998 CHIP Bias Sun Jan 11 20:08:14 GMT 1998 CHIP End Bias Sun Jan 11 20:08:22 GMT 1998 CHIP Water Sun Jan 11 20:09:01 GMT 1998 CHIP End Water WEATHER COMMENT: Sun Jan 11 20:17:40 GMT 1998 Thin cirrostratus still present. MKIII COMMENT: Sun Jan 11 20:17:56 GMT 1998 I try the dark shutter every 30 minutes at least and still haven't found it stuck vet. Sun Jan 11 21:00:12 GMT 1998 PICS Flat Sun Jan 11 21:01:02 GMT 1998 CHIP Bias Sun Jan 11 21:01:45 GMT 1998 End Flat PICS

CHIP

CHIP

End Bias

Water

Sun Jan 11 21:01:58 GMT 1998

Sun Jan 11 21:02:05 GMT 1998

Sun Jan 11 21:02:49 GMT 1998 CHIP End Water MKIII COMMENT: Sun Jan 11 21:03:52 GMT 1998 I couldn't get the dark shutter to stick so I took apart the drivetrain, it looked OK so I tightened the clutch about 1/4 revolution. This may cure problem, only time will tell since the problem is infrequent. Maybe the clutch is wearing down due to the new control system which may be driving the mechanism for too long after it stops, causing the clutch to slip a lot. I think we should cut back on the drive time to what is barely needed plus maybe two seconds, to extend the life of the clutch. PICS COMMENT: Sun Jan 11 21:27:51 GMT 1998 Stalled with Program: K-corona, not sure how long since I was up in the dome for a while working on MK3, fixed with Kill/Run. Sun Jan 11 21:43:35 GMT 1998 Start Patrol PICS Sun Jan 11 22:00:11 GMT 1998 Flat PICS Sun Jan 11 22:01:33 GMT 1998 End Flat PICS Sun Jan 11 22:03:05 GMT 1998 CHIP Bias Sun Jan 11 22:04:05 GMT 1998 CHIP End Bias Sun Jan 11 22:04:13 GMT 1998 CHIP Water Sun Jan 11 22:04:56 GMT 1998 CHIP End Water Sun Jan 11 22:46:08 GMT 1998 PICS End Patrol Sun Jan 11 22:47:34 GMT 1998 CHIP CHIP End Patrol Sun Jan 11 22:48:01 GMT 1998 CHIP ending tape COMMENT: Sun Jan 11 22:48:44 GMT 1998 TAPES: ***** MKIII: No data due to clouds PICS: P01083 CHIP: C00471 LOWL: L00491 in drive #0 Sun Jan 11 22:51:04 GMT 1998 MkIII