

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Mon Dec 19 17:31:57 GMT 2011

Year: 11 Doy: 353

Observer: berkey

WEATHER COMMENT: Mon Dec 19 17:33:08 GMT 2011

Blowing fog, temp 35f, wind 25mph from SE, parking look icy and slipppppppery

\_\_\_\_end\_\_\_\_

\*\*MKIV PROBLEM COMMENT BY BEN\*\* : Mon Dec 19 17:33:48 GMT 2011

KCC chassis has an electrical problem. The fans make a ticking sound and all of the lights blink on and off like there is a "brown" out situation

\_\_\_\_end\_\_\_\_

MKIV COMMENT BY BEN: Mon Dec 19 18:09:14 GMT 2011

I think the problem is related to circuit 2 on the DEC switched power supply in the back of the rack. I switched the VME rack from circuit 2 to circuit 1. Circuit 1 contains also powers all the other stuff, guider, control system rack, amplifiers etc.

\_\_\_\_end\_\_\_\_

NOTE BY BEN: Mon Dec 19 19:38:15 GMT 2011

Clouds starting to clear enough to see the sun, but there is a very threatening cloud bank about 1/2 a kilometer east of MLS 0 and looks ready to "attack" at any minute.

\_\_\_\_end\_\_\_\_

GONG COMMENT BY BEN: Mon Dec 19 21:50:13 GMT 2011

Gong pm done

\_\_\_\_end\_\_\_\_

Tue Dec 20 01:22:35 GMT 2011

MkIV