
Mauna Loa Solar Observatory Observer's Log

Fri Jun 19 16:19:50 GMT 2015

Year: 15 Doy: 170

Observer: berkey

WEATHER COMMENT: berkey: Fri Jun 19 16:22:46 GMT 2015

Temp: 46.4f, Humidity: 22%, Pressure: 28.621in, Wind: 10mph from the south, Skies: thin cirrus

____end____

WEATHER COMMENT: berkey: Fri Jun 19 16:22:58 GMT 2015

Temp: 46.5f, Humidity: 23%, Pressure: 28.625in, Wind: 13mph from 360deg, Skies:

____end____

WEATHER COMMENT: berkey: Fri Jun 19 16:23:01 GMT 2015

Temp: 46.4f, Humidity: 22%, Pressure: 28.621in, Wind: 10mph from the south, Skies: thin cirrus

____end____

GENERAL COMMENT BY berkey: Fri Jun 19 16:24:16 GMT 2015

Day 2 of kcor new camera plate install

____end____

KCOR COMMENT BY berkey: Fri Jun 19 20:04:36 GMT 2015

Optical alignment in tip/tilt is done. Taking some distortion masks flats.

____end____

Fri Jun 19 20:31:16 GMT 2015 COMP Start Patrol

KCOR COMMENT BY berkey: Fri Jun 19 21:01:54 GMT 2015

Yesterday we reverted to the old cameralink cable on the reflected beam. Today I could n't get socketcam running got lots of board acquisition errors on Brd1. Reverting to the old cable on this camera fixed this.

Taking distortion mask data on kcor from 20:59:24 to 21:00:57

____end____

COMP COMMENT BY berkey: Fri Jun 19 21:17:59 GMT 2015

I didn't notice it for a bit, but we took a bit of comp data on the inside of the dome shutter. So we should see a bit of junk over the last 15 minutes

____end____

KCOR COMMENT BY berkey: Fri Jun 19 21:55:31 GMT 2015

I tried to tidy up the cameralink cables and now I am having socketcam problems again.
:(

I tried rebooting and re-seating the cables a couple times no success.

Giving up for the day.

____end____

Fri Jun 19 21:56:28 GMT 2015 COMP End Patrol