```
--------------------------------------------------------------------------------
                   Mauna Loa Solar Observatory Observer's Log
--------------------------------------------------------------------------------
            Tue Feb  1 17:12:30 GMT 2000
Year: 00  Doy: 032
Observer: yasukawa
WEATHER COMMENT: Tue Feb  1 17:13:07 GMT 2000
Cold, clear, brisk south wind.
Tue Feb  1 17:16:59 GMT 2000     CHIP      Startup--Initializing new tape
PSPT COMMENT: Tue Feb  1 17:23:25 GMT 2000
PSPT data tape transfer successful overnight.
COMMENT: Tue Feb  1 17:26:30 GMT 2000
sky tx finally cleared dome wall, starting obs.
Tue Feb  1 17:26:41 GMT 2000     CHIP      CHIP Start Patrol
Tue Feb  1 17:27:03 GMT 2000     MKIV      Start Patrol
Tue Feb  1 18:00:26 GMT 2000     PICS      Flat
Tue Feb  1 18:03:03 GMT 2000     PICS      End Flat
Tue Feb  1 18:03:14 GMT 2000     CHIP      Bias
Tue Feb  1 18:04:22 GMT 2000     CHIP      End Bias
Tue Feb  1 18:04:42 GMT 2000     CHIP      Water
Tue Feb  1 18:05:29 GMT 2000     CHIP      End Water
Tue Feb  1 19:03:18 GMT 2000     CHIP      Bias
Tue Feb  1 19:04:25 GMT 2000     CHIP      End Bias
Tue Feb  1 19:04:47 GMT 2000     CHIP      Water
Tue Feb  1 19:05:34 GMT 2000     CHIP      End Water
**MLSO PROBLEM**: Tue Feb  1 19:56:10 GMT 2000
UPS just self tested.  Scary noise did not happen with the new EU.
Displayed message indicates that the battery charger has failed.
Tue Feb  1 20:03:08 GMT 2000     CHIP      Gain
Tue Feb  1 20:09:05 GMT 2000     CHIP      End Gain
Tue Feb  1 20:09:21 GMT 2000     CHIP      Bias
Tue Feb  1 20:10:23 GMT 2000     CHIP      End Bias
Tue Feb  1 20:10:34 GMT 2000     CHIP      Water
Tue Feb  1 20:11:15 GMT 2000     CHIP      End Water
**MLSO PROBLEM**: Tue Feb  1 20:31:52 GMT 2000
Followed reset procedure on UPS as outlined by Darryl.  Loosened thumbscrew
on rear of EU and broke contact between units, manipulated front panel
buttons as specified.  This turned off the beeps and the battery charger
failure message and returned to normal display.  The UPS started up with
a low, smoothe, groan, again, not as scary as before replacing the EU.
Tue Feb  1 21:03:09 GMT 2000     CHIP      Bias
Tue Feb  1 21:04:22 GMT 2000     CHIP      End Bias
Tue Feb  1 21:04:36 GMT 2000     CHIP      Water
Tue Feb  1 21:05:30 GMT 2000     CHIP      End Water
**MKIV PROBLEM**: Tue Feb  1 21:09:08 GMT 2000
2049 xanim image affected by possible bad sky on west limb.
2101 xanim image hosed.  2110 xanim image is rotated.
```

```
**MKIV PROBLEM**: Tue Feb  1 21:29:51 GMT 2000
2119 xanim image also hosed.
**MKIV PROBLEM**: Tue Feb  1 21:30:48 GMT 2000
I have not noticed any unusual raw images on the MCC display.
Tue Feb  1 22:03:09 GMT 2000    CHIP      Bias
Tue Feb  1 22:04:21 GMT 2000    CHIP      End Bias
Tue Feb  1 22:04:43 GMT 2000    CHIP      Water
Tue Feb  1 22:05:39 GMT 2000    CHIP      End Water
Tue Feb  1 22:07:13 GMT 2000    PICS      End Patrol
Tue Feb  1 22:08:32 GMT 2000    CHIP      CHIP End Patrol
Tue Feb  1 22:09:03 GMT 2000    CHIP      ending tape
COMMENT: Tue Feb  1 22:09:40 GMT 2000
Tapes:
MKIV:  00-032
PICS:  P01652
CHIP:  C01028
LOWL:  L00667
Tue Feb  1 22:11:42 GMT 2000
       MkIV


17_27.rawmk4    18_23.rawmk4    19_29.rawmk4    20_26.rawmk4    21_22.rawmk4
17_30.rawmk4    18_26.rawmk4    19_32.rawmk4    20_29.rawmk4    21_25.rawmk4
17_33.rawmk4    18_29.rawmk4    19_35.rawmk4    20_32.rawmk4    21_28.rawmk4
17_36.rawmk4    18_32.rawmk4    19_38.rawmk4    20_34.rawmk4    21_31.rawmk4
17_39.rawmk4    18_35.rawmk4    19_41.rawmk4    20_37.rawmk4    21_34.rawmk4
17_41.rawmk4    18_41.rawmk4    19_44.rawmk4    20_40.rawmk4    21_37.rawmk4
17_44.rawmk4    18_47.rawmk4    19_47.rawmk4    20_43.rawmk4    21_40.rawmk4
17_47.rawmk4    18_53.rawmk4    19_50.rawmk4    20_46.rawmk4    21_43.rawmk4
17_50.rawmk4    18_56.rawmk4    19_53.rawmk4    20_49.rawmk4    21_46.rawmk4
17_53.rawmk4    18_59.rawmk4    19_56.rawmk4    20_52.rawmk4    21_49.rawmk4
17_56.rawmk4    19_02.rawmk4    19_59.rawmk4    20_55.rawmk4    21_52.rawmk4
17_59.rawmk4    19_05.rawmk4    20_02.rawmk4    20_58.rawmk4    21_55.rawmk4
18_02.rawmk4    19_08.rawmk4    20_05.rawmk4    21_01.rawmk4    21_58.rawmk4
18_05.rawmk4    19_11.rawmk4    20_08.rawmk4    21_04.rawmk4    22_01.rawmk4
18_08.rawmk4    19_14.rawmk4    20_11.rawmk4    21_07.rawmk4    22_04.rawmk4
18_11.rawmk4    19_17.rawmk4    20_14.rawmk4    21_10.rawmk4    c18_38.rawmk4
18_14.rawmk4    19_20.rawmk4    20_17.rawmk4    21_13.rawmk4    c18_44.rawmk4
18_17.rawmk4    19_23.rawmk4    20_20.rawmk4    21_16.rawmk4    c18_50.rawmk4
18_20.rawmk4    19_26.rawmk4    20_23.rawmk4    21_19.rawmk4
```