## Mauna Loa Solar Observatory Observer's Log \_\_\_\_\_\_ Fri Oct 22 16:36:19 GMT 1999 Year: 99 Doy: 295 Observer: yasukawa WEATHER COMMENT: Fri Oct 22 16:37:12 GMT 1999 Cool, in broken cirrus, light south wind. Fri Oct 22 16:37:41 GMT 1999 CHIP Startup--Initializing new tape Fri Oct 22 16:49:55 GMT 1999 CHIP CHIP Start Patrol Fri Oct 22 16:50:18 GMT 1999 PICS Start Patrol Start Patrol Fri Oct 22 16:50:34 GMT 1999 MKIV \*\*LOW-L PROBLEM\*\*: Fri Oct 22 16:50:44 GMT 1999 Both tapes ejected from drives, qui still running, just indicating no tape online, 5 files indicated. Quit, cleaned both drives, keeping L00636, Loaded L00637 into drive #0, L00638 into drive #1. Restarted LOWL. Data writing to L00637 in drive #0. Fri Oct 22 17:03:02 GMT 1999 Bias Fri Oct 22 17:04:06 GMT 1999 CHIP End Bias Fri Oct 22 17:04:20 GMT 1999 CHIP Water Fri Oct 22 17:05:06 GMT 1999 End Water CHIP WEATHER COMMENT: Fri Oct 22 17:10:45 GMT 1999 In what looks like extensive thin cirrus. Cirrus coming from southwest so unable to determine if we'll be in it all day, checking satellite imagery. Running MKIV anyway but not getting any meaningful data at this time. Fri Oct 22 18:00:35 GMT 1999 Flat PICS Fri Oct 22 18:03:08 GMT 1999 PICS End Flat Fri Oct 22 18:03:08 GMT 1999 End Flat PICS Fri Oct 22 18:04:09 GMT 1999 End Bias CHIP Fri Oct 22 18:04:26 GMT 1999 CHIP Water Fri Oct 22 18:05:16 GMT 1999 CHIP End Water GONG COMMENT: Fri Oct 22 18:20:52 GMT 1999 GONG PM team are here to do semi-annual PM. Fri Oct 22 19:03:06 GMT 1999 CHIP Bias Fri Oct 22 19:04:18 GMT 1999 End Bias CHIP Fri Oct 22 19:04:40 GMT 1999 CHIP Water Fri Oct 22 19:05:28 GMT 1999 CHIP End Water \*\*MKIV PROBLEM\*\*: Fri Oct 22 19:46:40 GMT 1999 KCC crashed. Resetting. WEATHER COMMENT: Fri Oct 22 19:47:21 GMT 1999 In orographic clouds. Fri Oct 22 19:52:24 GMT 1999 PICS End Patrol \*\*MKIV PROBLEM\*\*: Fri Oct 22 19:52:40 GMT 1999 Reset didn't respond. Had to cycle KCC power to recover. Fri Oct 22 19:53:35 GMT 1999 CHIP CHIP End Patrol Fri Oct 22 20:14:47 GMT 1999 CHIP ending tape

COMMENT: Fri Oct 22 20:19:14 GMT 1999

```
Tapes:
```

MKIV: No useable data

CHIP: C00955 PICS: P01580

LOWL: L00637 in drive #0

\*\*MKIV PROBLEM\*\*: Fri Oct 22 20:23:55 GMT 1999

Received Card-designed plans and parts for the 60-Hz notch filter from Ron. Constructed filter on prototype board and coated it with Corning 3140 RTV to insulate bare wiring from contacting KCC chassis. Filter is curing on workbench. We will install and test it next time after the RTV cures.

Fri Oct 22 20:28:02 GMT 1999 MkIV

 16\_50.rawmk4
 17\_23.rawmk4
 17\_56.rawmk4
 18\_29.rawmk4
 19\_02.rawmk4

 16\_53.rawmk4
 17\_26.rawmk4
 17\_59.rawmk4
 18\_32.rawmk4
 19\_05.rawmk4

 16\_56.rawmk4
 17\_29.rawmk4
 18\_02.rawmk4
 18\_35.rawmk4
 19\_08.rawmk4

 16\_59.rawmk4
 17\_32.rawmk4
 18\_05.rawmk4
 18\_38.rawmk4
 19\_11.rawmk4

 17\_02.rawmk4
 17\_35.rawmk4
 18\_08.rawmk4
 18\_41.rawmk4
 19\_14.rawmk4

 17\_05.rawmk4
 17\_38.rawmk4
 18\_11.rawmk4
 18\_47.rawmk4
 19\_17.rawmk4

 17\_08.rawmk4
 17\_41.rawmk4
 18\_14.rawmk4
 18\_47.rawmk4
 19\_20.rawmk4

 17\_11.rawmk4
 17\_44.rawmk4
 18\_17.rawmk4
 18\_50.rawmk4
 19\_23.rawmk4

 17\_17.rawmk4
 17\_47.rawmk4
 18\_20.rawmk4
 18\_53.rawmk4
 19\_26.rawmk4

 17\_17.rawmk4
 17\_50.rawmk4
 18\_23.rawmk4
 18\_56.rawmk4
 19\_29.rawmk4

 17\_20.rawmk4
 17\_53.rawmk4
 18\_59.rawmk4
 19\_32.rawmk4