
Mauna Loa Solar Observatory Observer's Log

Tue Mar 18 17:24:11 GMT 2003

Year: 03 Doy: 077

Observer: koon

Tue Mar 18 17:27:57 GMT 2003 MKIV Start Patrol
Tue Mar 18 17:28:01 GMT 2003 CHIP Start Patrol
Tue Mar 18 17:28:10 GMT 2003 PICS Start Patrol

WEATHER COMMENT: Tue Mar 18 17:24:12 GMT 2003 Clear sky, wind=5 mph from the SE, temp=42 F.

Tue Mar 18 17:43:28 GMT 2003 MKIV Start Patrol

MKIV PROBLEM: Tue Mar 18 17:43:48 GMT 2003

Stalled at end of first scan, cycled main power rocker switch for KCC etc.

PSPT COMMENT: Tue Mar 18 17:46:48 GMT 2003

Observing.

MKIV COMMENT: Tue Mar 18 17:52:24 GMT 2003

Centered occulting.

Tue Mar 18 18:01:51 GMT 2003 CHIP LSD Tue Mar 18 18:03:48 GMT 2003 End LSD CHIP Tue Mar 18 18:03:57 GMT 2003 BiasLSD CHIP Tue Mar 18 18:04:02 GMT 2003 PICS Flat CHIP Tue Mar 18 18:04:53 GMT 2003 End BiasLSD Tue Mar 18 18:05:12 GMT 2003 Bias CHIP Tue Mar 18 18:06:15 GMT 2003 CHIP End Bias PICS End Flat

Tue Mar 18 18:06:32 GMT 2003 PICS COMMENT: Tue Mar 18 18:26:58 GMT 2003

Noticed pointing going off in declination, can see it in image displacement and on the meter display, reset dec to fix. The Dec clutch is tighter than usual since I adjusted it on Sunday. This is an experiment in progress. A NEW TAPE HAS BEEN PUT INTO KAIEE DLT DRIVE, Tue Mar 18 18:29:37 GMT 2003 MKIV COMMENT: Tue Mar 18 19:19:33 GMT 2003

Centered occulting.

COMMENT: Tue Mar 18 19:19:45 GMT 2003

I've been moving the spar around a bit for about an hour checking on a mk4 problem.

MKIV PROBLEM: Tue Mar 18 19:20:31 GMT 2003

Several times today the barrel has stalled at the end of the CCW scan, I found that if you push it slightly in the CW direction it will continue on with the CW scan. I checked out the camera heater cable and other wrapups and they all look good. Still checking out problem, seems like it may be caused by excess friction somewhere or a worn motor or clutch. Will be bumping things around a bit more as the day goes on.

COMMENT: Tue Mar 18 19:24:35 GMT 2003

Extended the slot.

PICS COMMENT: Tue Mar 18 19:26:07 GMT 2003

So far I haven't noticed any dust in the images, yesterday's cleaning looks successful.

```
**MKIV PROBLEM**: Tue Mar 18 19:46:59 GMT 2003
Stalled at end of CCW scan again, I turned the motor a few steps in the CCW
direction and the CW scan began. There is a strange looking sector in the
SE on the scans, will pause then cycle KCC main power to see if that clears it.
Tue Mar 18 19:51:18 GMT 2003
                               MKIV
                                        Start Patrol
**MKIV PROBLEM**: Tue Mar 18 19:53:29 GMT 2003
Found the cause of the strange sector, the tiltplate wasn't out all the way,
moved it out and all is well.
MKIV COMMENT: Tue Mar 18 19:54:20 GMT 2003
Centered occulting.
MKIV COMMENT: Tue Mar 18 21:25:21 GMT 2003
Centered occulting.
Tue Mar 18 21:43:06 GMT 2003
                               MKIV
                                        End Patrol
Tue Mar 18 21:43:16 GMT 2003
                                        Start Cal
                                MKIV
Tue Mar 18 22:02:01 GMT 2003
                                        End Cal
                               MKIV
Tue Mar 18 22:02:12 GMT 2003
                               MKIV
                                        Start Patrol
MKIV COMMENT: Tue Mar 18 22:43:19 GMT 2003
Centered occulting.
MKIV COMMENT: Tue Mar 18 23:46:03 GMT 2003
Centered occulting.
MKIV COMMENT: Wed Mar 19 00:59:35 GMT 2003
Centered occulting.
COMMENT: Wed Mar 19 00:59:55 GMT 2003
I haven't lost Dec guiding in the middle of the day today, maybe because of
the tightened clutch. But it wandered a little earlier in the day and I had
to reset the guider to fix it, but didn't have to do the typical running up
and down the stairs several times to fix it like we were doing around midday
before I tightened the clutch on Sunday.
**PSPT PROBLEM**: Wed Mar 19 01:39:57 GMT 2003
Stalled at "clr cak -- hope to help hang" GUI message. Killed renPspt.pro
and restarted. I'll run the diffuser tests Randy requested on Thursday, I
need more time to practice with some of the manual settings that gave me
trouble last time.
COMMENT: Wed Mar 19 02:20:32 GMT 2003
Extended the dome slot again.
Wed Mar 19 02:26:44 GMT 2003
                                         End Patrol
                                CHIP
Wed Mar 19 02:26:58 GMT 2003
                                PICS
                                         End Patrol
Wed Mar 19 02:27:55 GMT 2003
                                        End Patrol
                                MKIV
Wed Mar 19 02:36:21 GMT 2003
        MkIV
00 00.rawmk4
              01 43.rawmk4
                              18 40.rawmk4
                                             20 41.rawmk4
                                                            22 34.rawmk4
              01 46.rawmk4
00 03.rawmk4
                             18 54.rawmk4
                                             20 44.rawmk4
                                                            22 37.rawmk4
00 06.rawmk4
              01 49.rawmk4 18 59.rawmk4
                                             20 47.rawmk4
                                                            22 40.rawmk4
00 09.rawmk4
              01_52.rawmk4
                             19_01.rawmk4
                                             20 49.rawmk4
                                                            22 43.rawmk4
00 12.rawmk4
              01 55.rawmk4
                             19 04.rawmk4
                                             20 52.rawmk4
                                                            22 46.rawmk4
00 15.rawmk4
              01 58.rawmk4 19 07.rawmk4
                                             20 55.rawmk4
                                                            22 49.rawmk4
              02 01.rawmk4
00 18.rawmk4
                             19 10.rawmk4
                                             20 58.rawmk4
                                                            22 52.rawmk4
```

00 21.rawmk4	02 04.rawmk4	19 13.rawmk4	21 01.rawmk4	22 55.rawmk4
00 24.rawmk4	02 07.rawmk4		21 04.rawmk4	22 58.rawmk4
00_27.rawmk4	02 10.rawmk4	19 19.rawmk4	21 07.rawmk4	23 00.rawmk4
00_30.rawmk4	02_12.rawmk4	19_22.rawmk4	21_10.rawmk4	23_03.rawmk4
00_33.rawmk4	02_15.rawmk4	19_25.rawmk4	21_13.rawmk4	23_06.rawmk4
00_35.rawmk4	02_18.rawmk4	19_28.rawmk4	21_16.rawmk4	23_09.rawmk4
00_38.rawmk4	02_21.rawmk4	19_31.rawmk4	21_19.rawmk4	23_12.rawmk4
00_41.rawmk4	02_24.rawmk4	19_37.rawmk4	21_22.rawmk4	23_18.rawmk4
00_44.rawmk4	17_27.rawmk4	19_40.rawmk4	21_25.rawmk4	23_22.rawmk4
00_47.rawmk4	17_43.rawmk4	19_43.rawmk4	21_28.rawmk4	23_25.rawmk4
00_50.rawmk4	17_46.rawmk4	19_46.rawmk4	21_31.rawmk4	23_28.rawmk4
00_53.rawmk4	17_49.rawmk4	19_51.rawmk4	21_34.rawmk4	23_31.rawmk4
00_56.rawmk4	17_52.rawmk4	19_54.rawmk4	21_36.rawmk4	23_34.rawmk4
00_59.rawmk4	17_55.rawmk4	19_57.rawmk4	21_39.rawmk4	23_37.rawmk4
01_02.rawmk4	17_58.rawmk4	20_00.rawmk4	21_46.rawmk4	23_40.rawmk4
01_05.rawmk4	18_01.rawmk4	20_03.rawmk4	21_52.rawmk4	23_43.rawmk4
01_08.rawmk4	18_04.rawmk4	20_05.rawmk4	21_58.rawmk4	23_46.rawmk4
01_11.rawmk4	18_07.rawmk4	20_08.rawmk4	22_02.rawmk4	23_48.rawmk4
01_14.rawmk4	18_10.rawmk4	20_11.rawmk4	22_05.rawmk4	23_51.rawmk4
01_17.rawmk4	18_13.rawmk4	20_14.rawmk4	22_08.rawmk4	23_54.rawmk4
01_20.rawmk4	18_16.rawmk4	20_17.rawmk4	22_11.rawmk4	23_57.rawmk4
01_23.rawmk4	18_19.rawmk4	20_20.rawmk4	22_13.rawmk4	c21_43.rawmk4
01_25.rawmk4	18_22.rawmk4	20_23.rawmk4	22_16.rawmk4	c21_49.rawmk4
01_28.rawmk4	18_25.rawmk4	20_26.rawmk4	22_19.rawmk4	c21_55.rawmk4
01_31.rawmk4	18_27.rawmk4	20_29.rawmk4	22_22.rawmk4	
01_34.rawmk4	18_30.rawmk4	20_32.rawmk4	22_25.rawmk4	
01_37.rawmk4	18_33.rawmk4	20_35.rawmk4	22_28.rawmk4	
01_40.rawmk4	18_36.rawmk4	20_38.rawmk4	22_31.rawmk4	