
Mauna Loa Solar Observatory Observer's Log

Sun Jul 3 17:00:42 GMT 2011

Year: 11 Doy: 184

Observer: koon

WEATHER COMMENT: Sun Jul 3 17:00:44 GMT 2011

Clear sky, wind=15mph from the SE, temp=51F.

____end____

Sun Jul 3 17:06:18 GMT 2011 MKIV Start Patrol

Sun Jul 03 17:06:19 GMT 2011 H-ALPHA Start Patrol

MKIV PROBLEM COMMENT BY DARRYL: Sun Jul 3 17:07:48 GMT 2011

It took several tries to get the normal realtime GUI to come up this morning,
cycling the main KCC power.

____end____

Sun Jul 3 17:12:13 GMT 2011 CHIP Start Patrol

Sun Jul 03 17:14:15 GMT 2011 COMP Start Patrol

Sun Jul 3 17:33:42 GMT 2011: PSPT Start Patrol

Sun Jul 3 17:36:00 GMT 2011 MKIV End Patrol

Sun Jul 3 17:36:07 GMT 2011 MKIV Start Cal

Sun Jul 3 17:55:43 GMT 2011 MKIV Start Patrol

Sun Jul 3 18:00:40 GMT 2011 CHIP LSD

Sun Jul 3 18:02:11 GMT 2011 CHIP End LSD

Sun Jul 3 18:02:21 GMT 2011 CHIP BiasLSD

Sun Jul 3 18:03:00 GMT 2011 CHIP End BiasLSD

Sun Jul 3 18:03:08 GMT 2011 CHIP Bias

Sun Jul 3 18:03:52 GMT 2011 CHIP End Bias

Sun Jul 3 18:04:00 GMT 2011 CHIP ReStart Patrol

Sun Jul 03 20:06:50 GMT 2011 COMP End Patrol

Sun Jul 03 20:06:52 GMT 2011 COMP Start Patrol

Sun Jul 03 20:12:39 GMT 2011 COMP End Patrol

NOTE BY DARRYL: Sun Jul 3 20:16:37 GMT 2011

Adjusted dome slot opening.

____end____

Sun Jul 03 20:18:19 GMT 2011 COMP Start Patrol

NOTE BY DARRYL: Sun Jul 3 22:02:04 GMT 2011

Brought up more cleaning, sealing, lubing supplies that I bought recently.

Also brought up new Dayton motor and "starting capacitor" for PSPT

dome shutter. Might not need capacitor unless we notice that the motor

has a difficult time starting up and moving the dome shutter, if it moves

like normal then the old cap is still good.

____end____

NOTE BY DARRYL: Sun Jul 3 22:57:09 GMT 2011

Manually turned dome 180 degrees.

____end____

PSPT COMMENT BY DARRYL: Sun Jul 3 22:57:41 GMT 2011

New motor looks like it is an excellent replacement for the burnt-out motor
on the shutter. I put some notes on the wiring list someone made earlier

when they removed the old motor. Connector 2 on new motor looks like the equivalent of #4 on old motor, the rest looks like a match. I'd like Allen to double check that on Thursday to be safer, then Ben could install the motor on Friday maybe, it is on bench next to old motor, so is new capacitor in case we need that. We can hand crank the shutter for a few more days.

____end____
Sun Jul 3 23:01:42 GMT 2011 CHIP LSD
Sun Jul 3 23:03:15 GMT 2011 CHIP End LSD
Sun Jul 3 23:03:23 GMT 2011 CHIP BiasLSD
Sun Jul 3 23:03:57 GMT 2011 CHIP End BiasLSD
Sun Jul 3 23:04:07 GMT 2011 CHIP Bias
Sun Jul 3 23:04:54 GMT 2011 CHIP End Bias
Sun Jul 3 23:05:06 GMT 2011 CHIP ReStart Patrol
Sun Jul 03 23:10:18 GMT 2011 COMP End Patrol
Sun Jul 03 23:10:21 GMT 2011 COMP Start Patrol
Sun Jul 03 23:25:35 GMT 2011 COMP End Patrol
Sun Jul 03 23:30:15 GMT 2011 COMP Start Patrol
CoMP COMMENT BY DARRYL: Sun Jul 3 23:30:13 GMT 2011
Adjusted occulting near cookbook start, restarted cookbook.

____end____
Mon Jul 4 00:48:30 GMT 2011 CHIP End Patrol
Mon Jul 04 00:48:54 GMT 2011 COMP End Patrol
Mon Jul 4 00:48:49 GMT 2011: PSPT Abort Patrol
Mon Jul 4 00:49:28 GMT 2011 MKIV End Patrol
Mon Jul 04 00:49:49 GMT 2011 H-ALPHA End Patrol
NOTE BY DARRYL: Mon Jul 4 01:11:55 GMT 2011
Silicone lubed annoying loud squeaky wooden handles on PSPT manual shutter crank, lube is kept with other lubes in glass cabinet near electronics bench,

____end____
Mon Jul 4 01:14:56 GMT 2011
MkIV

00_01.rawmk4	18_04.rawmk4	19_35.rawmk4	21_10.rawmk4	22_41.rawmk4
00_07.rawmk4	18_07.rawmk4	19_38.rawmk4	21_13.rawmk4	22_44.rawmk4
00_10.rawmk4	18_10.rawmk4	19_41.rawmk4	21_16.rawmk4	22_47.rawmk4
00_13.rawmk4	18_13.rawmk4	19_44.rawmk4	21_19.rawmk4	22_50.rawmk4
00_16.rawmk4	18_16.rawmk4	19_47.rawmk4	21_22.rawmk4	22_53.rawmk4
00_19.rawmk4	18_19.rawmk4	19_50.rawmk4	21_25.rawmk4	22_56.rawmk4
00_22.rawmk4	18_22.rawmk4	19_56.rawmk4	21_28.rawmk4	22_59.rawmk4
00_25.rawmk4	18_25.rawmk4	20_00.rawmk4	21_31.rawmk4	23_02.rawmk4
00_28.rawmk4	18_28.rawmk4	20_03.rawmk4	21_34.rawmk4	23_05.rawmk4
00_31.rawmk4	18_30.rawmk4	20_05.rawmk4	21_37.rawmk4	23_08.rawmk4
00_34.rawmk4	18_33.rawmk4	20_08.rawmk4	21_40.rawmk4	23_11.rawmk4
00_37.rawmk4	18_36.rawmk4	20_11.rawmk4	21_43.rawmk4	23_14.rawmk4
00_40.rawmk4	18_39.rawmk4	20_14.rawmk4	21_45.rawmk4	23_17.rawmk4
00_43.rawmk4	18_42.rawmk4	20_17.rawmk4	21_48.rawmk4	23_20.rawmk4
00_46.rawmk4	18_45.rawmk4	20_20.rawmk4	21_51.rawmk4	23_23.rawmk4
17_06.rawmk4	18_48.rawmk4	20_23.rawmk4	21_54.rawmk4	23_26.rawmk4

17_09.rawmk4	18_51.rawmk4	20_26.rawmk4	21_57.rawmk4	23_28.rawmk4
17_12.rawmk4	18_54.rawmk4	20_29.rawmk4	22_00.rawmk4	23_31.rawmk4
17_15.rawmk4	18_57.rawmk4	20_32.rawmk4	22_03.rawmk4	23_34.rawmk4
17_18.rawmk4	19_00.rawmk4	20_35.rawmk4	22_06.rawmk4	23_37.rawmk4
17_21.rawmk4	19_03.rawmk4	20_38.rawmk4	22_09.rawmk4	23_40.rawmk4
17_24.rawmk4	19_06.rawmk4	20_41.rawmk4	22_12.rawmk4	23_43.rawmk4
17_26.rawmk4	19_09.rawmk4	20_44.rawmk4	22_15.rawmk4	23_46.rawmk4
17_29.rawmk4	19_12.rawmk4	20_47.rawmk4	22_18.rawmk4	23_49.rawmk4
17_32.rawmk4	19_15.rawmk4	20_50.rawmk4	22_21.rawmk4	23_52.rawmk4
17_39.rawmk4	19_17.rawmk4	20_52.rawmk4	22_24.rawmk4	23_55.rawmk4
17_45.rawmk4	19_20.rawmk4	20_55.rawmk4	22_27.rawmk4	23_58.rawmk4
17_51.rawmk4	19_23.rawmk4	20_58.rawmk4	22_30.rawmk4	c17_36.rawmk4
17_55.rawmk4	19_26.rawmk4	21_01.rawmk4	22_32.rawmk4	c17_42.rawmk4
17_58.rawmk4	19_29.rawmk4	21_04.rawmk4	22_35.rawmk4	c17_48.rawmk4
18_01.rawmk4	19_32.rawmk4	21_07.rawmk4	22_38.rawmk4	