
Mauna Loa Solar Observatory Observer's Log

Wed Jul 10 16:13:14 GMT 2013

Year: 13 Doy: 191

Observer: rose

WEATHER COMMENT: Wed Jul 10 16:13:39 GMT 2013

clear sky, wind 10-15mph SE, 45F

\006__end__

Wed Jul 10 16:45:20 GMT 2013: PSPT Start Patrol

Wed Jul 10 16:51:04 GMT 2013 CHIP Start Patrol

Wed Jul 10 16:52:12 GMT 2013 COMP Start Patrol

Wed Jul 10 17:17:25 GMT 2013: PSPT Abort Patrol

Wed Jul 10 17:17:34 GMT 2013: PSPT Start Patrol

Wed Jul 10 17:21:44 GMT 2013 Wed Jul 10 18:00:40 GMT 2013 CHIP LSD

Wed Jul 10 18:02:28 GMT 2013 CHIP End LSD

Wed Jul 10 18:02:34 GMT 2013 CHIP BiasLSD

Wed Jul 10 18:03:09 GMT 2013 CHIP End BiasLSD

Wed Jul 10 18:03:16 GMT 2013 CHIP Bias

Wed Jul 10 18:03:47 GMT 2013 CHIP End Bias

Wed Jul 10 18:03:52 GMT 2013 CHIP ReStart Patrol

Wed Jul 10 18:10:50 GMT 2013: PSPT Start Patrol

Wed Jul 10 18:13:59 GMT 2013

Wed Jul 10 20:05:17 GMT 2013 CHIP End Patrol

NOTE BY GREG: Wed Jul 10 20:04:24 GMT 2013

reconfigured dome shutter

__end__

Wed Jul 10 20:10:34 GMT 2013 CHIP Start Patrol

Wed Jul 10 20:09:52 GMT 2013 MKIV Start Patrol

CoMP PROBLEM COMMENT BY BEN: Wed Jul 10 20:13:15 GMT 2013

During an inspection of the spar for access issues during the mk4 decommissioning I caught and pinched the CoMP rockwell camera -> lake shore temp controller cable on part of the RA dog house.

Wire 3 was some how broken.

Greg cut the bad section off and we pulled new wire up from bundle ontop of the CoMP rack. Inital tests showed the cable to be good so Greg is cleaning it up now.

Please note that we have been touching and accessing the spar, so many of the observations this may have been either miss pointed or otherwise shaken.

__end__

Wed Jul 10 20:36:03 GMT 2013 CHIP End Patrol

Wed Jul 10 20:36:34 GMT 2013 CHIP Start Patrol

Wed Jul 10 20:39:18 GMT 2013 COMP Start Patrol

CHIP PROBLEM COMMENT BY BEN: Wed Jul 10 20:40:52 GMT 2013

Adjusting chip Y motor,

__end__

CoMP PROBLEM COMMENT BY GREG: Wed Jul 10 20:48:06 GMT 2013

A wire was stained while measuring the spar. It was the lakeshore camera temperature sensor. The wire was long so the are

a that was broken was removed and a new connector was installed. works again

____end____

GONG COMMENT BY BEN: Wed Jul 10 21:00:07 GMT 2013

Gong monthly pm done

____end____

NOTE BY BEN: Wed Jul 10 22:17:30 GMT 2013

Spar couldn't track the sun in Dec. Looks like the cable bundle was pulling the top of the spar slightly south. A small lead block (~5#) was added to the north side on the bottom of the spar. And the cables were fussed with to restore tracking

____end____

Wed Jul 10 23:00:40 GMT 2013 CHIP LSD
Wed Jul 10 23:02:28 GMT 2013 CHIP End LSD
Wed Jul 10 23:02:37 GMT 2013 CHIP BiasLSD
Wed Jul 10 23:03:39 GMT 2013 CHIP End BiasLSD
Wed Jul 10 23:03:52 GMT 2013 CHIP Bias
Wed Jul 10 23:06:52 GMT 2013 CHIP Start Patrol
Wed Jul 10 23:38:14 GMT 2013 COMP End Patrol
Wed Jul 10 23:38:16 GMT 2013 COMP Start Patrol
Thu Jul 11 01:33:49 GMT 2013: PSPT Abort Patrol
Thu Jul 11 01:34:05 GMT 2013: PSPT Abort Patrol
Thu Jul 11 01:38:03 GMT 2013 CHIP End Patrol
Thu Jul 11 01:38:44 GMT 2013 COMP End Patrol
Thu Jul 11 01:39:58 GMT 2013 MKIV End Patrol
Thu Jul 11 01:46:51 GMT 2013

MkIV

00_02.rawmk4 01_30.rawmk4 19_37.rawmk4 21_14.rawmk4 22_43.rawmk4
00_05.rawmk4 01_33.rawmk4 19_40.rawmk4 21_17.rawmk4 22_46.rawmk4
00_08.rawmk4 01_36.rawmk4 19_46.rawmk4 21_20.rawmk4 22_48.rawmk4
00_11.rawmk4 18_17.rawmk4 19_49.rawmk4 21_23.rawmk4 22_51.rawmk4
00_14.rawmk4 18_20.rawmk4 19_52.rawmk4 21_26.rawmk4 22_54.rawmk4
00_17.rawmk4 18_23.rawmk4 19_55.rawmk4 21_29.rawmk4 22_57.rawmk4
00_20.rawmk4 18_26.rawmk4 19_58.rawmk4 21_32.rawmk4 23_00.rawmk4
00_23.rawmk4 18_29.rawmk4 20_01.rawmk4 21_35.rawmk4 23_03.rawmk4
00_26.rawmk4 18_32.rawmk4 20_09.rawmk4 21_38.rawmk4 23_06.rawmk4
00_29.rawmk4 18_35.rawmk4 20_12.rawmk4 21_41.rawmk4 23_09.rawmk4
00_31.rawmk4 18_38.rawmk4 20_15.rawmk4 21_44.rawmk4 23_12.rawmk4
00_34.rawmk4 18_41.rawmk4 20_18.rawmk4 21_47.rawmk4 23_15.rawmk4
00_37.rawmk4 18_44.rawmk4 20_21.rawmk4 21_49.rawmk4 23_18.rawmk4
00_40.rawmk4 18_47.rawmk4 20_24.rawmk4 21_52.rawmk4 23_21.rawmk4
00_43.rawmk4 18_50.rawmk4 20_27.rawmk4 21_55.rawmk4 23_24.rawmk4
00_46.rawmk4 18_53.rawmk4 20_30.rawmk4 21_58.rawmk4 23_27.rawmk4
00_49.rawmk4 18_55.rawmk4 20_33.rawmk4 22_01.rawmk4 23_30.rawmk4
00_52.rawmk4 18_58.rawmk4 20_36.rawmk4 22_04.rawmk4 23_33.rawmk4
00_55.rawmk4 19_01.rawmk4 20_39.rawmk4 22_07.rawmk4 23_36.rawmk4
00_58.rawmk4 19_04.rawmk4 20_42.rawmk4 22_10.rawmk4 23_39.rawmk4
01_01.rawmk4 19_07.rawmk4 20_45.rawmk4 22_13.rawmk4 23_41.rawmk4
01_04.rawmk4 19_10.rawmk4 20_48.rawmk4 22_16.rawmk4 23_44.rawmk4
01_07.rawmk4 19_13.rawmk4 20_51.rawmk4 22_19.rawmk4 23_47.rawmk4

01_10.rawmk4	19_16.rawmk4	20_54.rawmk4	22_22.rawmk4	23_50.rawmk4
01_13.rawmk4	19_19.rawmk4	20_57.rawmk4	22_25.rawmk4	23_53.rawmk4
01_16.rawmk4	19_22.rawmk4	21_00.rawmk4	22_28.rawmk4	23_56.rawmk4
01_19.rawmk4	19_25.rawmk4	21_02.rawmk4	22_31.rawmk4	23_59.rawmk4
01_22.rawmk4	19_28.rawmk4	21_05.rawmk4	22_34.rawmk4	
01_24.rawmk4	19_31.rawmk4	21_08.rawmk4	22_37.rawmk4	
01_27.rawmk4	19_34.rawmk4	21_11.rawmk4	22_40.rawmk4	