```
Mauna Loa Solar Observatory Observer's Log
 ______
      Tue Jun 9 16:31:14 GMT 2015
Year: 15 Doy: 160
Observer: stueben
WEATHER COMMENT: stueben: Tue Jun 9 16:31:22 GMT 2015
Clear, wind southeast 5-10 mph, temp 47F.
end
Tue Jun 09 16:48:27 GMT 2015 COMP Start Patrol
Tue Jun 09 16:56:27 GMT 2015 KCOR Start Synoptic Patrol
Tue Jun 09 18:08:28 GMT 2015 KCOR End Patrol
Tue Jun 09 18:08:29 GMT 2015 KCOR Start Calibration script: c:\kcor\mlso-calibration22deq-20150323.ini
Tue Jun 09 18:25:44 GMT 2015 KCOR End Calibration Script
Tue Jun 09 18:26:01 GMT 2015 KCOR Start Synoptic Patrol
Tue Jun 09 18:26:01 GMT 2015 KCOR Start Synoptic Patrol
Tue Jun 09 20:42:48 GMT 2015 COMP End Patrol
Tue Jun 09 20:47:28 GMT 2015 KCOR End Patrol
Tue Jun 09 20:59:35 GMT 2015 COMP Start Patrol
Tue Jun 09 20:59:55 GMT 2015 KCOR Start Synoptic Patrol
GENERAL OBSERVATORY COMMENT BY stueben: Tue Jun 9 21:01:19 GMT 2015
Reconfigured dome shutter and adjusted sqs offsets.
WEATHER COMMENT: stueben: Tue Jun 9 21:02:02 GMT 2015
Orographic clouds are beginning to degrade images.
end
Tue Jun 09 22:19:50 GMT 2015 COMP End Patrol
Tue Jun 09 22:20:25 GMT 2015 KCOR End Patrol
WEATHER COMMENT: stueben: Tue Jun 9 22:22:32 GMT 2015
In clouds, instruments idled.
end
Tue Jun 09 23:52:47 GMT 2015 COMP Start Patrol
Tue Jun 09 23:55:15 GMT 2015 KCOR Start Synoptic Patrol
Tue Jun 09 23:58:06 GMT 2015 CoMP Paused for clouds
Wed Jun 10 00:02:48 GMT 2015 CoMP Restarted from pause
Wed Jun 10 00:09:58 GMT 2015 KCOR End Patrol
Wed Jun 10 00:11:18 GMT 2015 CoMP Paused for clouds
Wed Jun 10 00:19:57 GMT 2015 CoMP Restarted from pause
Wed Jun 10 00:20:17 GMT 2015 COMP End Patrol
WEATHER COMMENT: stueben: Wed Jun 10 01:13:26 GMT 2015
Blowing fog.
 end
**PSPT PROBLEM COMMENT BY stueben**: Wed Jun 10 01:14:04 GMT 2015
I haven't been able to get pspt running today. It points to the sun well but
hangs up in the center sun routine when it tries to center the image on the ccd.
It doesn't appear to be getting the image data. I looked at the J64 connector
which we repaired recently and it looks OK. I also swapped in our spare FO cable
and FO converter, but the problem persists.
```

____end___