```
Mauna Loa Solar Observatory Observer's Log
       Wed Feb 15 16:58:27 GMT 2017
Year: 17 Doy: 046
Observer: berkey
WEATHER COMMENT: berkey: Wed Feb 15 16:59:55 GMT 2017
Temp: 39.6f, Humidity: 45%, Pressure: 28.77in, Wind: 7mph from 211degs, Skies: clear
 end
Wed Feb 15 17:47:40 GMT 2017 SGS Alignment complete
Wed Feb 15 17:48:08 GMT 2017 CoMP occulter has been re-centered
Wed Feb 15 17:48:09 GMT 2017 COMP Start Patrol on cookbook: synoptic-00010.cbk
Wed Feb 15 17:48:14 GMT 2017 COMP End Patrol
Wed Feb 15 17:51:53 GMT 2017 Kcor Focus/alignment program exited
Wed Feb 15 17:52:11 GMT 2017 COMP Start Patrol on cookbook: synoptic-00010.cbk
Wed Feb 15 18:08:17 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 19:13:22 GMT 2017 KCOR End Patrol
Wed Feb 15 19:13:23 GMT 2017 KCOR Start Calibration script: c:\kcor\mlso-calibration22deq-20150323.ini
Wed Feb 15 19:30:36 GMT 2017 KCOR End Calibration Script
Wed Feb 15 19:30:53 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 19:30:54 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 19:30:54 GMT 2017 KCOR End Patrol
Wed Feb 15 19:30:56 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 20:33:29 GMT 2017 KCOR End Patrol
Wed Feb 15 20:33:49 GMT 2017 COMP End Patrol
Wed Feb 15 20:35:21 GMT 2017 SGS Alignment complete
Wed Feb 15 20:35:42 GMT 2017 CoMP occulter has been re-centered
Wed Feb 15 20:36:26 GMT 2017 Kcor Focus/alignment program exited
Wed Feb 15 20:37:07 GMT 2017 COMP Start Patrol on cookbook: synoptic-00010.cbk
Wed Feb 15 20:37:12 GMT 2017 COMP End Patrol
Wed Feb 15 20:37:12 GMT 2017 COMP Start Patrol on cookbook: waves-00001.cbk
Wed Feb 15 20:48:21 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 22:09:38 GMT 2017 COMP End Patrol
Wed Feb 15 22:09:38 GMT 2017 COMP Start Patrol on cookbook: synoptic-00010.cbk
Wed Feb 15 23:13:38 GMT 2017 Kcor sees an SGS Guiding Error closing lens cover
Wed Feb 15 23:13:40 GMT 2017 KCOR End Patrol
GENERAL COMMENT BY berkey: Wed Feb 15 23:15:27 GMT 2017
Clouds snuck up on my. I didn't notice coming on any of the webcams.
   end
Wed Feb 15 23:16:47 GMT 2017 CoMP Paused for clouds
Wed Feb 15 23:18:08 GMT 2017 CoMP Restarted from pause
Wed Feb 15 23:24:08 GMT 2017 KCOR Start Synoptic Patrol
Wed Feb 15 23:24:51 GMT 2017 KCOR End Patrol
Wed Feb 15 23:25:21 GMT 2017 CoMP Paused for clouds
```

Wed Feb 15 23:28:05 GMT 2017 CoMP Restarted from pause Wed Feb 15 23:28:34 GMT 2017 CoMP Paused for clouds GENERAL COMMENT BY berkey: Thu Feb 16 02:39:45 GMT 2017

The building camera was having some auto exposure issues and producing some images that are almost completely white. Thes e seem to have been charasiticly ~49k in size. So I have updated the script that copys these files to the server to ignore these small files for now while I try to understand the root cause of the problem. But for now the ignore small files fi xe, has helped made the webcam video look better.

\_\_\_\_end\_\_\_

GENERAL COMMENT BY berkey: Thu Feb 16 02:42:02 GMT 2017

Dome rotation has a new audible vibration that sounds to be coming from the interaction of the slip rings and contact fing ers. There is no obvious cause to this problem and it doesn't seem like this system is in a dangerous state. So I have a n email in to ash support looking for more sight to the problem.

\_\_\_\_end\_\_\_