
Mauna Loa Solar Observatory Observer's Log

Tue Jun 9 16:31:14 GMT 2015

Year: 15 Doy: 160

Observer: stueben

WEATHER COMMENT: stueben: Tue Jun 9 16:31:22 GMT 2015

Clear, wind southeast 5-10 mph, temp 47F.

____end____

Tue Jun 09 16:48:27 GMT 2015 COMP Start Patrol

Tue Jun 09 16:56:27 GMT 2015 KCOR Start Synoptic Patrol

Tue Jun 09 18:08:28 GMT 2015 KCOR End Patrol

Tue Jun 09 18:08:29 GMT 2015 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20150323.ini

Tue Jun 09 18:25:44 GMT 2015 KCOR End Calibration Script

Tue Jun 09 18:26:01 GMT 2015 KCOR Start Synoptic Patrol

Tue Jun 09 18:26:01 GMT 2015 KCOR Start Synoptic Patrol

Tue Jun 09 20:42:48 GMT 2015 COMP End Patrol

Tue Jun 09 20:47:28 GMT 2015 KCOR End Patrol

Tue Jun 09 20:59:35 GMT 2015 COMP Start Patrol

Tue Jun 09 20:59:55 GMT 2015 KCOR Start Synoptic Patrol

GENERAL OBSERVATORY COMMENT BY stueben: Tue Jun 9 21:01:19 GMT 2015

Reconfigured dome shutter and adjusted sgs offsets.

____end____

WEATHER COMMENT: stueben: Tue Jun 9 21:02:02 GMT 2015

Orographic clouds are beginning to degrade images.

____end____

Tue Jun 09 22:19:50 GMT 2015 COMP End Patrol

Tue Jun 09 22:20:25 GMT 2015 KCOR End Patrol

WEATHER COMMENT: stueben: Tue Jun 9 22:22:32 GMT 2015

In clouds, instruments idled.

____end____

Tue Jun 09 23:52:47 GMT 2015 COMP Start Patrol

Tue Jun 09 23:55:15 GMT 2015 KCOR Start Synoptic Patrol

Tue Jun 09 23:58:06 GMT 2015 CoMP Paused for clouds

Wed Jun 10 00:02:48 GMT 2015 CoMP Restarted from pause

Wed Jun 10 00:09:58 GMT 2015 KCOR End Patrol

Wed Jun 10 00:11:18 GMT 2015 CoMP Paused for clouds

Wed Jun 10 00:19:57 GMT 2015 CoMP Restarted from pause

Wed Jun 10 00:20:17 GMT 2015 COMP End Patrol

WEATHER COMMENT: stueben: Wed Jun 10 01:13:26 GMT 2015

Blowing fog.

____end____

PSPT PROBLEM COMMENT BY stueben : Wed Jun 10 01:14:04 GMT 2015

I haven't been able to get pspt running today. It points to the sun well but hangs up in the center sun routine when it tries to center the image on the ccd. It doesn't appear to be getting the image data. I looked at the J64 connector which we repaired recently and it looks OK. I also swapped in our spare FO cable and FO converter, but the problem persists.

____end____