
Mauna Loa Solar Observatory Observer's Log

Sat Oct 21 16:52:47 GMT 2017

Year: 17 Doy: 294

Observer: stueben

WEATHER COMMENT: stueben: Sat Oct 21 16:56:34 GMT 2017

Temp: 43.5f, Humidity: 13%, Pressure: 28.741in, Wind: South 5-10 mph, Skies: Thin cirrus covers most of the sky at present.

____end____

KCOR COMMENT BY stueben: Sat Oct 21 17:13:19 GMT 2017

PM Blew off Kcor 01 front.

____end____

CoMP COMMENT BY stueben: Sat Oct 21 17:13:58 GMT 2017

PM Blew off CoMP 01.

____end____

Sat Oct 21 19:32:20 GMT 2017 Kcor Focus/alignment program exited

Sat Oct 21 23:02:34 GMT 2017 CoMP occulter has been re-centered

****CoMP PROBLEM COMMENT BY stueben**** : Sun Oct 22 00:01:35 GMT 2017

I removed the remaining part of the difuser assembly from comp. Removed the motor/gear box and then separated the motor from the gearbox. Both the motor and gearbox move freely, so at this point the greatest likelihood seems to be that the driver electronics integrated into the motor have failed.

____end____

WEATHER COMMENT: stueben: Sun Oct 22 00:48:04 GMT 2017

Orographic clouds beneath cirrus.

____end____

GENERAL COMMENT BY stueben: Sun Oct 22 01:04:13 GMT 2017

No data today, cloudy all day.

____end____