Mon Mar 14 17:45:34 GMT 1994 Year: 94 Doy: 073 Observer: koon

COMMENT: Mon Mar 14 17:45:49 GMT 1994 Clear sky, temp=45 F, wind  $\sim$ 20 mph from the south.

Mon Mar 14 17:47:19 GMT 1994: Patrol Start

COMMENT: Mon Mar 14 17:52:55 GMT 1994 LOW-L COMMENT: The tape in drive #1 was apparently filled and ejected normally, however the tape in drive #2 was ejected also - apparently too early. I put the latest tape into drive #1 and the program proceeded to write to it normally. Since this is a recurring problem I will switch tape drive #2 with our spare drive.

Mon Mar 14 18:00:17 GMT 1994: Filemark-Calibration

## DPMON COMMENT: Mon Mar 14 18:02:49 GMT 1994

Changed the daystar filter temp setting from 5.9 to 6.0. NOTE: the diffuser was in the light path since I started up the PMon, I left it in to see if it would be moved out during the hourly calibration, it was removed OK. The way I removed it the last time this happened was to shutdown and restart the PMon, I thought the problem was related to my using "tip modem" at the same time as the cal last time but this time I didn't use "tip modem" and the problem existed before the hourly cal.

## COMMENT: Mon Mar 14 18:35:28 GMT 1994

LOWL-L COMMENT: Replaced tape drive #1 (not #2, drives are defined as #0 and #1). Removed tape from tape drive #0 (not #1 as previously mentioned) so that I could test connection/termination and drive number assignment for the newly installed drive #1. All appears to be working fine, we are now getting data again.

Mon Mar 14 19:00:19 GMT 1994: Filemark-Calibration

DPMON COMMENT: Mon Mar 14 19:43:24 GMT 1994 Changed the daystar filter setting from 6.0 to 6.1 30 minutes ago.

DPMON COMMENT: Mon Mar 14 19:59:19 GMT 1994 Getting occassional surges at PA=70.

Mon Mar 14 20:00:16 GMT 1994: Filemark-Calibration

DPMON COMMENT: Mon Mar 14 20:09:44 GMT 1994 Changed daystar filter temp from 6.1 to 6.2.

DPMON COMMENT: Mon Mar 14 20:50:59 GMT 1994 Medium sized surge at PA=70 out to about RV=1.1.

Mon Mar 14 21:00:16 GMT 1994: Filemark-Calibration

DPMON COMMENT: Mon Mar 14 21:14:14 GMT 1994 Changed Daystar filter temp setting back to 5.0 from 6.2.

Mon Mar 14 21:35:05 GMT 1994: Patrol End

DPMON COMMENT: Mon Mar 14 21:36:16 GMT 1994 Starting to get dome interference in declination, looks like we'll have to start opening the slot extension around 11:15. Closing down for today.

COMMENT: Mon Mar 14 21:42:13 GMT 1994 Activity report: QP: 245; 277. AP: PA~70, RV~1.1 No coronal activity.

TAPES: MKIII: H00720 DPMON: P00020 LOW-L: Removed L00010, started L00011.

Mon Mar 14 21:45:45 GMT 1994: Filemark SAN-LOG SAN-LOG ? SCAN-LOG SCAN-LOG 17:36:55. 3/14/94 DOY 73 17:42:08 17:45:23 17:48:36 17:51:50 17:55:02 17:58:15 18:01:26 18:04:39 18:07:49 18:11:01 18:14:12 18:17:25 18:20:36 18:23:49 18:27:01 18:30:16 18:33:28 18:36:41 18:39:52 18:43:06 18:46:19 18:49:31 18:52:42 18:55:53 18:59:04 19:02:16 19:05:26 19:08:39 19:11:50 19:15:02 19:21:25 19:18:14 1928 O CL 19:48:07 1952 15CL 20:00:39 20:03:51 20:07:02 20:10:11 20:13:21 20:16:30 20:19:40 20:22:49 20:26:00 20:29:08 20:32:18 20:35:26 20:38:35 20:41:43 20:44:52 20:48:01 20:51:13 20:54:20 20:57:29 21:00:35 21:03:43 21:06:49 21:09:56 21:13:04 21:16:17 21:19:23 21:22:31 21:25:37 21:28:46 21:31:52

21:35:00 21:38:07

0 ERRORS

OK