

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Thu Dec 13 17:19:46 GMT 2001

Year: 01 Doy: 347

Observer: koon

WEATHER COMMENT: Thu Dec 13 17:19:50 GMT 2001

Snowing and raining, 1-2" of snow on ground, luckily the rain is keeping the ice away so I could drive all the way up - barely.

COMMENT: Thu Dec 13 17:20:51 GMT 2001

Placed buckets under the roof leaks. It looks like the power hasn't been interrupted yet.

WEATHER COMMENT: Thu Dec 13 21:50:07 GMT 2001

Snowing all day.

**\*\*PICS PROBLEM\*\***: Thu Dec 13 21:50:17 GMT 2001

I swapped the HOME\_NC and HOME\_NO wires before the assembly side connector. This fixed the reverse-Home problem, hopefully it will help with the timeout problems we sometimes see.

PICS COMMENT: Thu Dec 13 22:03:24 GMT 2001

PICS is back together and ready to use.

Thu Dec 13 22:18:05 GMT 2001

MkIV