
Mauna Loa Solar Observatory Observer's Log

Fri Oct 25 17:07:52 GMT 2002

Year: 02 Doy: 298 Observer: stueben

WEATHER COMMENT: Fri Oct 25 17:08:12 GMT 2002 broken cirrus, south wind 25-30mph, temp 45F

Fri Oct 25 17:11:09 GMT 2002 CHIP Start Patrol Fri Oct 25 17:11:35 GMT 2002 PICS Start Patrol Fri Oct 25 17:11:49 GMT 2002 MKIV Start Patrol

PSPT COMMENT: Fri Oct 25 17:29:39 GMT 2002

pspt started but then stopped due to cloud density

PSPT PROBLEM: Fri Oct 25 17:36:59 GMT 2002

Cannot hear shutter operating. Shutter was replaced yesterday and replacement shutter worked all day. Shutting PSPT down and checking shutter.

PSPT PROBLEM: Fri Oct 25 17:55:49 GMT 2002

Removed shutter and tested it outside of PSPT. Initially the shutter was not staying open. Tested the last spare and it did stay open when NC/NO switch was toggled to NO. Tested current shutter again and it functioned OK this time. Reinstalled surrent shutter and starting PSPT up again.

Fri Oct 25 18:01:56 GMT 2002 PICS Flat
Fri Oct 25 18:02:46 GMT 2002 CHIP LSD
Fri Oct 25 18:04:23 GMT 2002 PICS End Flat
Fri Oct 25 18:04:40 GMT 2002 CHIP End LSD
Fri Oct 25 18:04:49 GMT 2002 CHIP BiasLSD

PSPT COMMENT: Fri Oct 25 18:04:02 GMT 2002

Restart OK. Earlier startup problem was shutter intermittent failure rather than thick clouds—they are thick, though. Starting daily observations.

Fri Oct 25 18:05:42 GMT 2002 CHIP End BiasLSD

Fri Oct 25 18:05:57 GMT 2002 CHIP Bias Fri Oct 25 18:06:59 GMT 2002 CHIP End Bias

**** EVENT COMMENT ****: Fri Oct 25 18:06:16 GMT 2002

Active region on northwest quadrant of disk flaring beginning at 1738 UT.

PSPT PROBLEM: Fri Oct 25 18:08:44 GMT 2002

Shutter failing again. Removing the spare we installed yesterday and installing second spare shutter.

PSPT PROBLEM: Fri Oct 25 18:20:49 GMT 2002

Replacement appears to be working OK.

PSPT PROBLEM: Fri Oct 25 19:28:46 GMT 2002

Noticed that Vincent Associates is closed on Fridays according to the invoice with the spares. Couldn't call them for RMA # today. Found their web site. Learned from their website that they moved on 10/7. Called FEDEX and they used the tracking number of yesterday's package to try to intercept the first shutter and route it to the new address. I also found Vincent Assoc.'s email address so I emailed them a request for an RMA # for the second shutter and also requested warranty repair on the unit since it failed after around 5 hours of operation after the last warranty repair—even though it was

stored as a spare since 12/2000. Awaiting a response and an RMA # before shipping second unit back.

Unit removed: s/n 1376 Unit installed: s/n 984 Unit in transit: s/n 1374 (yesterday's failure) MKIV COMMENT: Fri Oct 25 21:52:07 GMT 2002 Stopping MK4. No coronal data today, in cirrostratus all morning. Fri Oct 25 21:54:52 GMT 2002 MKIV End Patrol End Patrol Fri Oct 25 21:59:47 GMT 2002 PICS PSPT COMMENT: Fri Oct 25 22:01:14 GMT 2002 Stopped pspt. Fri Oct 25 22:07:18 GMT 2002 End Patrol CHIP Fri Oct 25 22:21:01 GMT 2002 MkIV 17 11.rawmk4 18 11.rawmk4 19 09.rawmk4 20 08.rawmk4 21 07.rawmk4 17 15.rawmk4 18 13.rawmk4 19 12.rawmk4 20 11.rawmk4 21 10.rawmk4 17 17.rawmk4 18 16.rawmk4 19 15.rawmk4 20 14.rawmk4 21 13.rawmk4 20_17.rawmk4 21_16.rawmk4 20_20.rawmk4 21_19.rawmk4 17 26.rawmk4 18 25.rawmk4 19 24.rawmk4 20 23.rawmk4 21 22.rawmk4 20_26.rawmk4 21_25.rawmk4 20 29.rawmk4 21 28.rawmk4 17 32.rawmk4 18 31.rawmk4 19 30.rawmk4 17 35.rawmk4 18 34.rawmk4 19 33.rawmk4 20 32.rawmk4 21 31.rawmk4 17 38.rawmk4 18 37.rawmk4 19 36.rawmk4 20 35.rawmk4 21 33.rawmk4 17 41.rawmk4 18 40.rawmk4 19 39.rawmk4 20 38.rawmk4 21 36.rawmk4 17 44.rawmk4 18 43.rawmk4 19 42.rawmk4 20 41.rawmk4 21 39.rawmk4 20_44.rawmk4 21_42.rawmk4 20 46.rawmk4 21 45.rawmk4 17 53.rawmk4 18 52.rawmk4 19 51.rawmk4 20 49.rawmk4 21 48.rawmk4 20_52.rawmk4 21_51.rawmk4 20 55.rawmk4 18 02.rawmk4 19 00.rawmk4 19 59.rawmk4 20 58.rawmk4 18 05.rawmk4 19 03.rawmk4 20 02.rawmk4 21 01.rawmk4 18 08.rawmk4 19 06.rawmk4 20 05.rawmk4 21 04.rawmk4