\_\_\_\_\_\_

## Mauna Loa Solar Observatory Observer's Log

\_\_\_\_\_\_

Wed Aug 20 16:29:29 GMT 2003

Year: 03 Doy: 232 Observer: yasukawa

WEATHER COMMENT: Wed Aug 20 16:30:28 GMT 2003

Cool, clear, light south wind. Scattered cirrus to west. Wed Aug 20 16:35:39 GMT 2003 CHIP Start Patrol

Wed Aug 20 16:35:57 GMT 2003 PICS Start Patrol

A NEW TAPE HAS BEEN PUT INTO KAIEE DLT DRIVE, Wed Aug 20 16:41:14 GMT 2003

MKIV COMMENT: Wed Aug 20 16:58:05 GMT 2003 mk4 cleared dome cylinder, Centering 01.

Wed Aug 20 16:58:28 GMT 2003 MKIV Start Patrol

PSPT COMMENT: Wed Aug 20 17:06:13 GMT 2003

Starting up.

\*\*PSPT PROBLEM\*\*: Wed Aug 20 17:06:37 GMT 2003

Removed and inspected the swapped Red and CaK filters and the Blue filter that was left in its correct station. With heater left on overnight, Red filter that was in the CaK position was heavily hazed as we expected. CaK filter that was left in the Red position was relatively clean. Blue filter was partially (~2/3 of area) hazed as before. Cleaned all ND filters and installed filters into their correct stations before starting up. PSPT COMMENT: Wed Aug 20 17:14:08 GMT 2003 Starting daily obs.

\*\*PSPT PROBLEM\*\*: Wed Aug 20 17:25:36 GMT 2003

Just replaced hatch cover. I was watching the positions move past the optical path.

\*\*PSPT PROBLEM\*\*: Wed Aug 20 17:40:25 GMT 2003

When in overnight stow position, blocked station is positioned over optical path. Other blocked station is partially in hatch location and Blue filter is also partially in hatch location. Blue filter is next to one of the heater rods. Next filter around is the CaK filter that is positioned next to the other heater rod. Next filter is the Red filter which is positioned distally to the hatch and is not positioned next to any heater rod. This is probably why the Red filter is not normally hazed over whereas the CaK and the Blue filters are hazed over. During normal operations, observing, the filters do not spend a lot of time sitting near the heater rods.

MKIV COMMENT: Wed Aug 20 17:57:23 GMT 2003

Centered 01.

Wed Aug 20 18:02:44 GMT 2003 CHIP LSD Wed Aug 20 18:02:52 GMT 2003 PICS Flat Wed Aug 20 18:04:22 GMT 2003 CHIP End LSD Wed Aug 20 18:04:38 GMT 2003 CHIP BiasLSD Wed Aug 20 18:05:17 GMT 2003 PICS End Flat Wed Aug 20 18:05:41 GMT 2003 CHIP End BiasLSD Wed Aug 20 18:05:50 GMT 2003 CHIP Bias

Wed Aug 20 18:06:43 GMT 2003 CHIP End Bias MKIV COMMENT: Wed Aug 20 18:59:15 GMT 2003 Centered 01. Wed Aug 20 19:03:13 GMT 2003 Start Cal COMMENT: Wed Aug 20 19:21:25 GMT 2003 Stopping to reconfigure dome shutter. Wed Aug 20 19:21:40 GMT 2003 CHIP End Patrol Wed Aug 20 19:22:02 GMT 2003 MKIV End Cal Wed Aug 20 19:24:37 GMT 2003 PICS End Patrol MKIV COMMENT: Wed Aug 20 19:32:27 GMT 2003 Centered 01. Wed Aug 20 19:32:25 GMT 2003 CHIP Start Patrol Wed Aug 20 19:32:39 GMT 2003 MKIV Start Patrol Wed Aug 20 19:32:30 GMT 2003 PICS Start Patrol MKIV COMMENT: Wed Aug 20 20:31:33 GMT 2003 Centered 01. WEATHER COMMENT: Wed Aug 20 21:22:15 GMT 2003 In thin cirrostratus, sky bright close to sun. MKIV COMMENT: Wed Aug 20 21:39:11 GMT 2003 Centered O1. Bright sky looks evenly bright around the sun. \*\*PSPT PROBLEM\*\*: Wed Aug 20 22:08:42 GMT 2003 Stopped observations. I will attempt to remove insulation material from the filter wheel area. \*\*PSPT PROBLEM\*\*: Wed Aug 20 22:20:34 GMT 2003 Turned off heater. Removed filters and checked ND pre-filters. All were relative clean. WEATHER COMMENT: Wed Aug 20 22:22:49 GMT 2003 in scattered orographic clouds. Thu Aug 21 01:12:56 GMT 2003 CHIP End Patrol WEATHER COMMENT: Thu Aug 21 01:13:05 GMT 2003 Panic dome closure. Was working on PSPT when it suddenly started raining off dark clouds to east which I did not notice due to shutter pointing west. Thu Aug 21 01:15:40 GMT 2003 End Patrol PICS Thu Aug 21 01:17:22 GMT 2003 MKIV End Patrol \*\*PSPT PROBLEM\*\*: Thu Aug 21 01:39:40 GMT 2003 Removed all insulation from inside of filter wheel cavity after removing the filters for safe-keeping. Removed as much of the RTV adhesive as possible. Cleaned out the debris with Wet-Swabs (isopropyl alcohol soaked foam-tipped wands) and reassembled the PSPT. Turned heaters back on after shutting PSPT down for the night. Darryl will check if the hazing is still occurring without the neoprene-like insulation. WEATHER COMMENT: Thu Aug 21 02:00:03 GMT 2003

Cloudburst has past, sky is now very clear except for thick altostratus cloud just to west of sun.

Shutting down so I can clean up the PSPT platform and put away tools.

COMMENT: Thu Aug 21 02:02:23 GMT 2003

Checked instruments. Although rain was pouring into the dome slot at the peak of the cloudburst (PSPT flap was still open for a while), no rain got onto the PSPT or onto the MK4/PICS/CHIP due to the direction the slots were facing when the wind-driven rain began. I got tops of the shutters closed and the spars moved before the rain became real heavy.

Ols did not get any raindrops on them.

Thu Aug 21 02:08:07 GMT 2003

MkIV

00 00 14	10 16 14	10 50 14	00.46	00 21 14
00_00.rawmk4	17_16.rawmk4	18_50.rawmk4	20_46.rawmk4	22_31.rawmk4
00_03.rawmk4	17_19.rawmk4	18_53.rawmk4	20_49.rawmk4	22_34.rawmk4
00_06.rawmk4	17_22.rawmk4	18_56.rawmk4	20_52.rawmk4	22_37.rawmk4
00_09.rawmk4	17_24.rawmk4	18_59.rawmk4	20_54.rawmk4	22_40.rawmk4
00_12.rawmk4	17_27.rawmk4	19_06.rawmk4	20_57.rawmk4	22_43.rawmk4
00_15.rawmk4	17_30.rawmk4	19_12.rawmk4	21_00.rawmk4	22_46.rawmk4
00_18.rawmk4	17_33.rawmk4	19_18.rawmk4	21_03.rawmk4	22_49.rawmk4
00_21.rawmk4	17_36.rawmk4	19_32.rawmk4	21_06.rawmk4	22_52.rawmk4
00_24.rawmk4	17_39.rawmk4	19_35.rawmk4	21_09.rawmk4	22_55.rawmk4
00_27.rawmk4	17_42.rawmk4	19_38.rawmk4	21_12.rawmk4	22_58.rawmk4
00_30.rawmk4	17_45.rawmk4	19_41.rawmk4	21_15.rawmk4	23_01.rawmk4
00_33.rawmk4	17_48.rawmk4	19_44.rawmk4	21_18.rawmk4	23_03.rawmk4
00_36.rawmk4	17_51.rawmk4	19_47.rawmk4	21_21.rawmk4	23_06.rawmk4
00_38.rawmk4	17_54.rawmk4	19_50.rawmk4	21_24.rawmk4	23_09.rawmk4
00_41.rawmk4	17_57.rawmk4	19_53.rawmk4	21_27.rawmk4	23_12.rawmk4
00_44.rawmk4	18_00.rawmk4	19_56.rawmk4	21_30.rawmk4	23_15.rawmk4
00_47.rawmk4	18_03.rawmk4	19_59.rawmk4	21_33.rawmk4	23_18.rawmk4
00 50.rawmk4	18_06.rawmk4	20 02.rawmk4	21 36.rawmk4	23 21.rawmk4
00_53.rawmk4	18 09.rawmk4	20 05.rawmk4	21 39.rawmk4	23 24.rawmk4
00 56.rawmk4	18 12.rawmk4	20 08.rawmk4	21 42.rawmk4	23 27.rawmk4
00 59.rawmk4	18 15.rawmk4	20 10.rawmk4	21 44.rawmk4	23 30.rawmk4
01 02.rawmk4			21 47.rawmk4	23 33.rawmk4
01 05.rawmk4	18 20.rawmk4	20 16.rawmk4	21 50.rawmk4	23 36.rawmk4
01 08.rawmk4	18 23.rawmk4	20 19.rawmk4	21 53.rawmk4	23 39.rawmk4
01_11.rawmk4	18_26.rawmk4	20_22.rawmk4	21_56.rawmk4	23_42.rawmk4
01 14.rawmk4	18 29.rawmk4	20 25.rawmk4	21 59.rawmk4	23 48.rawmk4
16 58.rawmk4	18 32.rawmk4	20 28.rawmk4	22 02.rawmk4	23 51.rawmk4
17_01.rawmk4	18_35.rawmk4	20 31.rawmk4	22_08.rawmk4	23 54.rawmk4
17 04.rawmk4	18 38.rawmk4	20 34.rawmk4	22 12.rawmk4	23 57.rawmk4
17_01.rawmk4	18 41.rawmk4	20_31.rawmk4	22_12.rawmk4	c19 03.rawmk4
17 10.rawmk4	18 44.rawmk4	20_37.1awmk1 20_40.rawmk4	22_10.rawmk1 22_22.rawmk4	c19 09.rawmk4
17_10.rawmk4	18 47.rawmk4	20_40.rawmk4	22_22.rawmk4 22_27.rawmk4	c19_05.rawmk4
1,_13.1awiik4	TO_T/.TawiilK4	20_43.1awiik4	ZZ_Z/.Iawiik4	CI9_IJ.IAWIIK4