
Mauna Loa Solar Observatory Observer's Log

Tue Nov 11 17:17:33 GMT 2003

Year: 03 Doy: 315

Observer: koon

WEATHER COMMENT: Tue Nov 11 17:17:39 GMT 2003

Thin cirrostratus overcast, wind=5 mph from the SE, temp=44 F.

Tue Nov 11 17:22:01 GMT 2003 MKIV Start Patrol

MKIV PROBLEM: Tue Nov 11 17:18:08 GMT 2003

Had problems logging into Nahenahe this morning. The screen was black and I couldn't get a login screen even after cycling the monitor or main KCC power switches several times each. Rlogin from Kii showed Stueben account was logged in, I became superuser and did a "sync, sync, halt" sequence then the Nahenahe screen became usable again. From there I did a "boot" on the Nahenahe screen to reboot Nahenahe. After that I could login like usual. This is the first time I've seen this problem.

MKIV COMMENT: Tue Nov 11 17:32:39 GMT 2003

Centered occulting.

ECHO COMMENT: Tue Nov 11 17:34:28 GMT 2003

Time OK.

PSPT COMMENT: Tue Nov 11 17:34:52 GMT 2003

Observing.

A NEW TAPE HAS BEEN PUT INTO KAIEE DLT DRIVE, Tue Nov 11 17:35:53 GMT 2003

Tue Nov 11 17:57:43 GMT 2003 MKIV End Patrol

Tue Nov 11 17:57:54 GMT 2003 MKIV Start Cal

Tue Nov 11 18:00:58 GMT 2003 CHIP LSD

Tue Nov 11 18:02:53 GMT 2003 CHIP End LSD

Tue Nov 11 18:03:02 GMT 2003 CHIP BiasLSD

Tue Nov 11 18:03:33 GMT 2003 PICS Flat

Tue Nov 11 18:03:55 GMT 2003 CHIP End BiasLSD

Tue Nov 11 18:04:08 GMT 2003 CHIP Bias

Tue Nov 11 18:05:06 GMT 2003 CHIP End Bias

Tue Nov 11 18:05:58 GMT 2003 PICS End Flat

Tue Nov 11 18:17:35 GMT 2003 MKIV Start Patrol

MKIV COMMENT: Tue Nov 11 19:36:52 GMT 2003

Centered occulting.

COMMENT: Tue Nov 11 20:34:34 GMT 2003

Rick Anthes of UCAR is here with his wife for a tour.

MKIV COMMENT: Tue Nov 11 20:35:55 GMT 2003

Centered occulting.

COMMENT: Tue Nov 11 20:57:02 GMT 2003

Lost Dec guiding, repointed and reset guiding.

MKIV PROBLEM: Tue Nov 11 20:59:54 GMT 2003

The two blue connectors at the back end were knocked loose so the barrel has stopped rotating for now.

MKIV PROBLEM: Tue Nov 11 21:32:04 GMT 2003

Fixed the connectors and reattached, restarted scans. The wires to

those connectors may have snagged on something, they were loose and bent and came off easily today. I was able to reuse them. I shortened the wire loops to reduce the chance of snags.

MKIV COMMENT: Tue Nov 11 21:33:20 GMT 2003

Centered occulting.

Tue Nov 11 21:38:37 GMT 2003 MKIV End Patrol

Tue Nov 11 21:38:49 GMT 2003 MKIV Start Patrol

MKIV COMMENT: Tue Nov 11 23:59:23 GMT 2003

Centered occulting.

MKIV COMMENT: Wed Nov 12 00:54:06 GMT 2003

Centered occulting.

MKIV COMMENT: Wed Nov 12 02:04:38 GMT 2003

Centered occulting.

Wed Nov 12 02:19:02 GMT 2003 CHIP End Patrol

Wed Nov 12 02:19:28 GMT 2003 PICS End Patrol

Wed Nov 12 02:22:40 GMT 2003 MKIV End Patrol

Wed Nov 12 02:33:29 GMT 2003

MkIV

00_01.rawmk4	01_44.rawmk4	18_38.rawmk4	20_21.rawmk4	22_30.rawmk4
00_04.rawmk4	01_46.rawmk4	18_41.rawmk4	20_23.rawmk4	22_33.rawmk4
00_07.rawmk4	01_49.rawmk4	18_44.rawmk4	20_26.rawmk4	22_35.rawmk4
00_10.rawmk4	01_52.rawmk4	18_47.rawmk4	20_29.rawmk4	22_38.rawmk4
00_12.rawmk4	01_55.rawmk4	18_49.rawmk4	20_32.rawmk4	22_41.rawmk4
00_15.rawmk4	01_58.rawmk4	18_52.rawmk4	20_35.rawmk4	22_44.rawmk4
00_18.rawmk4	02_01.rawmk4	18_55.rawmk4	20_38.rawmk4	22_47.rawmk4
00_21.rawmk4	02_04.rawmk4	18_58.rawmk4	20_41.rawmk4	22_50.rawmk4
00_24.rawmk4	02_07.rawmk4	19_01.rawmk4	20_44.rawmk4	22_53.rawmk4
00_27.rawmk4	02_10.rawmk4	19_04.rawmk4	20_47.rawmk4	22_56.rawmk4
00_30.rawmk4	02_13.rawmk4	19_07.rawmk4	20_50.rawmk4	22_59.rawmk4
00_33.rawmk4	02_16.rawmk4	19_10.rawmk4	20_53.rawmk4	23_02.rawmk4
00_36.rawmk4	02_19.rawmk4	19_13.rawmk4	20_56.rawmk4	23_05.rawmk4
00_39.rawmk4	17_22.rawmk4	19_16.rawmk4	21_11.rawmk4	23_08.rawmk4
00_42.rawmk4	17_25.rawmk4	19_19.rawmk4	21_17.rawmk4	23_11.rawmk4
00_45.rawmk4	17_28.rawmk4	19_22.rawmk4	21_22.rawmk4	23_14.rawmk4
00_48.rawmk4	17_30.rawmk4	19_25.rawmk4	21_30.rawmk4	23_17.rawmk4
00_51.rawmk4	17_33.rawmk4	19_28.rawmk4	21_35.rawmk4	23_20.rawmk4
00_54.rawmk4	17_36.rawmk4	19_31.rawmk4	21_38.rawmk4	23_22.rawmk4
00_57.rawmk4	17_39.rawmk4	19_33.rawmk4	21_41.rawmk4	23_25.rawmk4
01_00.rawmk4	17_42.rawmk4	19_36.rawmk4	21_44.rawmk4	23_28.rawmk4
01_02.rawmk4	17_45.rawmk4	19_39.rawmk4	21_47.rawmk4	23_31.rawmk4
01_05.rawmk4	17_48.rawmk4	19_42.rawmk4	21_50.rawmk4	23_34.rawmk4
01_08.rawmk4	17_51.rawmk4	19_45.rawmk4	21_53.rawmk4	23_37.rawmk4
01_11.rawmk4	17_54.rawmk4	19_48.rawmk4	21_56.rawmk4	23_40.rawmk4
01_14.rawmk4	18_01.rawmk4	19_51.rawmk4	21_59.rawmk4	23_43.rawmk4
01_17.rawmk4	18_07.rawmk4	19_54.rawmk4	22_02.rawmk4	23_46.rawmk4
01_20.rawmk4	18_13.rawmk4	19_57.rawmk4	22_05.rawmk4	23_49.rawmk4
01_23.rawmk4	18_17.rawmk4	20_00.rawmk4	22_08.rawmk4	23_52.rawmk4

01_26.rawmk4	18_20.rawmk4	20_03.rawmk4	22_11.rawmk4	23_55.rawmk4
01_29.rawmk4	18_23.rawmk4	20_06.rawmk4	22_14.rawmk4	23_58.rawmk4
01_32.rawmk4	18_26.rawmk4	20_09.rawmk4	22_17.rawmk4	c17_57.rawmk4
01_35.rawmk4	18_29.rawmk4	20_12.rawmk4	22_20.rawmk4	c18_04.rawmk4
01_38.rawmk4	18_32.rawmk4	20_15.rawmk4	22_23.rawmk4	c18_10.rawmk4
01_41.rawmk4	18_35.rawmk4	20_18.rawmk4	22_27.rawmk4	