
Mauna Loa Solar Observatory Observer's Log

Fri Jul 21 16:55:33 GMT 2006

Year: 06 Doy: 202

Observer: koon

Fri Jul 21 17:00:55 GMT 2006 CHIP Start Patrol

Fri Jul 21 17:01:09 GMT 2006 PICS Start Patrol

WEATHER COMMENT: Fri Jul 21 16:55:34 GMT 2006

Clear sky, wind=2 mph from the West, temp=44F.

____end____

SBM COMMENT: Fri Jul 21 17:03:32 GMT 2006

Obs.

____end____

PSPT COMMENT: Fri Jul 21 17:03:45 GMT 2006

Obs

____end____

Fri Jul 21 17:24:27 GMT 2006

MkIV

Fri Jul 21 17:27:56 GMT 2006 MKIV Start Patrol

MKIV PROBLEM: Fri Jul 21 17:27:18 GMT 2006

Startup problem. The Barrel was staying at CW limit, I used GUI to move it to CCW limit then cycled main KCC rocker switch, got same result with barrel staying at CW limit, when I clicked on "Begin Day" the barrel started moving CCW at a very slow rate of 30 instead of regular 240. With barrel off of CW limit I did a "pau" to kill processes then cycled main KCC power again, then did a "run" after the GUI screen came up and the barrel started moving automatically. This brought the instrument back to normality. I had to do a pau/run cycle a few days ago because data weren't being taken. Maybe Nahanaha needs to be rebooted, or maybe I need to wait until the startup script is done as indicated by a message in the akamai window at lower left before I start the "run" command.

____end____

Fri Jul 21 17:40:06 GMT 2006 MKIV End Patrol

Fri Jul 21 17:40:11 GMT 2006 MKIV Start Cal

WEATHER COMMENT: Fri Jul 21 17:48:19 GMT 2006

Cirrus clouds passing over.

____end____

Fri Jul 21 17:59:41 GMT 2006 MKIV Start Patrol

Fri Jul 21 18:01:52 GMT 2006 CHIP LSD

Fri Jul 21 18:02:12 GMT 2006 PICS Flat

Fri Jul 21 18:03:33 GMT 2006 CHIP End LSD

Fri Jul 21 18:03:42 GMT 2006 CHIP BiasLSD

Fri Jul 21 18:04:24 GMT 2006 CHIP End BiasLSD

Fri Jul 21 18:04:32 GMT 2006 CHIP Bias

Fri Jul 21 18:04:37 GMT 2006 PICS End Flat

Fri Jul 21 18:04:46 GMT 2006 PICS ReStart Patrol

Fri Jul 21 18:05:17 GMT 2006 CHIP End Bias

Fri Jul 21 18:05:31 GMT 2006 CHIP ReStart Patrol
MKIV COMMENT: Fri Jul 21 18:42:49 GMT 2006
Pausing due to clouds.

___end___
Fri Jul 21 18:47:00 GMT 2006 MKIV End Patrol
SBM COMMENT: Fri Jul 21 18:46:45 GMT 2006
Paused due to clouds.

___end___
Fri Jul 21 19:45:43 GMT 2006 CHIP End Patrol
Fri Jul 21 19:46:02 GMT 2006 PICS End Patrol
NICE CHIP IMAGE: 1731
NICE MK4 IMAGE: 1733
NICE PICSDISC IMAGE: 1728
NICE PICSLIMB IMAGE: 1734
Fri Jul 21 20:27:59 GMT 2006
MkIV

17_27.rawmk4	17_55.rawmk4	18_14.rawmk4	18_32.rawmk4	c17_46.rawmk4
17_30.rawmk4	17_59.rawmk4	18_17.rawmk4	18_35.rawmk4	c17_52.rawmk4
17_33.rawmk4	18_02.rawmk4	18_20.rawmk4	18_37.rawmk4	
17_36.rawmk4	18_05.rawmk4	18_23.rawmk4	18_40.rawmk4	
17_43.rawmk4	18_08.rawmk4	18_26.rawmk4	18_43.rawmk4	
17_49.rawmk4	18_11.rawmk4	18_29.rawmk4	c17_40.rawmk4	