
Mauna Loa Solar Observatory Observer's Log

Wed Nov 5 17:22:32 GMT 2008

Year: 08 Doy: 310

Observer: yasukawa

WEATHER COMMENT: Wed Nov 5 17:22:35 GMT 2008

In thick cirrostratus overcast, SE wind 7 mph, temp 41 F.

____end____

PSPT COMMENT: Wed Nov 5 18:31:48 GMT 2008

Starting up.

____end____

Wed Nov 5 18:32:11 GMT 2008 CHIP Start Patrol

WEATHER COMMENT: Wed Nov 5 18:32:14 GMT 2008

Overcast thinning and possibly moving out.

____end____

Wed Nov 5 18:34:54 GMT 2008 PICS Start Patrol

Wed Nov 5 18:46:39 GMT 2008 MKIV Start Patrol

PSPT PROBLEM Wed Nov 5 18:48:17 GMT 2008

Crashed starting up. K/r

____end____

PSPT COMMENT: Wed Nov 5 19:13:52 GMT 2008

Observing.

____end____

Wed Nov 5 19:16:23 GMT 2008 MKIV End Patrol

Wed Nov 5 19:16:28 GMT 2008 MKIV Start Cal

Wed Nov 5 19:35:10 GMT 2008 MKIV End Cal

Wed Nov 5 19:35:16 GMT 2008 MKIV Start Patrol

WEATHER COMMENT: Wed Nov 5 21:07:40 GMT 2008

Back in cirrus/cirrostratus again, thin now, thicker incoming.

Standing down with MK4.

____end____

Wed Nov 5 21:09:33 GMT 2008 MKIV End Patrol

NICE MK4 IMAGE: 1919

NICE CHIP IMAGE: 1920

NICE PICSLIMB IMAGE: 1917

NICE PICSDISC IMAGE: 1920

Wed Nov 5 21:33:14 GMT 2008 MKIV Start Patrol

Wed Nov 5 21:39:23 GMT 2008 MKIV End Patrol

Wed Nov 5 21:50:19 GMT 2008 MKIV Start Patrol

COMMENT: Thu Nov 6 01:02:57 GMT 2008

Discovered one of the reasons for the strained "cabling" in the late afternoon. The two hoses on the East side of the pier had fallen down through a loose wooden clamp due to a stripped hold-down screw.

Replacement screws and wooden clamps are inside the pier (opening on the west side). Replaced stripped screw, pulled the hoses up to provide a more generous loop, and tightened down the clamp.

____end____

Thu Nov 6 02:25:59 GMT 2008 PICS End Patrol
Thu Nov 6 02:26:53 GMT 2008 MKIV End Patrol
Thu Nov 6 02:26:42 GMT 2008 CHIP End Patrol
Thu Nov 6 02:32:51 GMT 2008

MkIV

00_02.rawmk4	01_27.rawmk4	19_13.rawmk4	20_48.rawmk4	22_49.rawmk4
00_05.rawmk4	01_30.rawmk4	19_19.rawmk4	20_51.rawmk4	22_51.rawmk4
00_08.rawmk4	01_33.rawmk4	19_25.rawmk4	20_54.rawmk4	22_54.rawmk4
00_11.rawmk4	01_36.rawmk4	19_31.rawmk4	20_57.rawmk4	22_57.rawmk4
00_14.rawmk4	01_39.rawmk4	19_35.rawmk4	21_00.rawmk4	23_00.rawmk4
00_17.rawmk4	01_42.rawmk4	19_38.rawmk4	21_03.rawmk4	23_03.rawmk4
00_20.rawmk4	01_45.rawmk4	19_41.rawmk4	21_06.rawmk4	23_06.rawmk4
00_23.rawmk4	01_48.rawmk4	19_44.rawmk4	21_33.rawmk4	23_09.rawmk4
00_25.rawmk4	01_51.rawmk4	19_47.rawmk4	21_36.rawmk4	23_12.rawmk4
00_28.rawmk4	01_54.rawmk4	19_50.rawmk4	21_50.rawmk4	23_15.rawmk4
00_31.rawmk4	01_57.rawmk4	19_52.rawmk4	21_53.rawmk4	23_18.rawmk4
00_34.rawmk4	01_59.rawmk4	19_55.rawmk4	21_56.rawmk4	23_21.rawmk4
00_37.rawmk4	02_02.rawmk4	19_58.rawmk4	21_59.rawmk4	23_24.rawmk4
00_40.rawmk4	02_05.rawmk4	20_01.rawmk4	22_02.rawmk4	23_27.rawmk4
00_43.rawmk4	02_08.rawmk4	20_04.rawmk4	22_05.rawmk4	23_30.rawmk4
00_46.rawmk4	02_11.rawmk4	20_07.rawmk4	22_07.rawmk4	23_33.rawmk4
00_49.rawmk4	02_14.rawmk4	20_10.rawmk4	22_10.rawmk4	23_35.rawmk4
00_52.rawmk4	02_17.rawmk4	20_13.rawmk4	22_13.rawmk4	23_38.rawmk4
00_55.rawmk4	02_20.rawmk4	20_16.rawmk4	22_16.rawmk4	23_41.rawmk4
00_58.rawmk4	02_23.rawmk4	20_19.rawmk4	22_19.rawmk4	23_44.rawmk4
01_01.rawmk4	18_46.rawmk4	20_22.rawmk4	22_22.rawmk4	23_47.rawmk4
01_04.rawmk4	18_49.rawmk4	20_25.rawmk4	22_25.rawmk4	23_50.rawmk4
01_07.rawmk4	18_52.rawmk4	20_28.rawmk4	22_28.rawmk4	23_53.rawmk4
01_10.rawmk4	18_55.rawmk4	20_31.rawmk4	22_31.rawmk4	23_56.rawmk4
01_12.rawmk4	18_58.rawmk4	20_34.rawmk4	22_34.rawmk4	23_59.rawmk4
01_15.rawmk4	19_01.rawmk4	20_36.rawmk4	22_37.rawmk4	c19_16.rawmk4
01_18.rawmk4	19_04.rawmk4	20_39.rawmk4	22_40.rawmk4	c19_22.rawmk4
01_21.rawmk4	19_07.rawmk4	20_42.rawmk4	22_43.rawmk4	c19_28.rawmk4
01_24.rawmk4	19_10.rawmk4	20_45.rawmk4	22_46.rawmk4	