
```
Mauna Loa Solar Observatory Observer's Log
```

Tue Sep 13 17:17:28 GMT 2011 Year: 11 Doy: 256 Observer: koon WEATHER COMMENT: Tue Sep 13 17:17:31 GMT 2011 Clear sky, wind=6mph from the SW, temp=45F. end Tue Sep 13 17:29:02 GMT 2011 CHIP Start Patrol Tue Sep 13 17:29:21 GMT 2011 H-ALPHA Start Patrol Tue Sep 13 17:35:45 GMT 2011 MKIV Start Patrol NOTE BY DARRYL: Tue Sep 13 17:36:42 GMT 2011 On Sunday I removed the old FAX machine and connected the new multi-function machine to the FAX phone line, the old machine is by the spare UNIX machines nears the PSPT control console, it still works and can be a backup spare. end COMP COMMENT BY DARRYL: Tue Sep 13 17:38:14 GMT 2011 On Sunday I tested the vacuum pump w/o connecting it to the CoMP, it worked well so I'll try to use it today to improve the vacuum in CoMP. end Tue Sep 13 17:40:39 GMT 2011: PSPT Start Patrol Tue Sep 13 17:54:43 GMT 2011 MKIV Start Cal Tue Sep 13 18:02:37 GMT 2011 CHIP LSD Tue Sep 13 18:04:13 GMT 2011 CHIP End LSD Tue Sep 13 18:04:21 GMT 2011 CHIP BiasLSD Tue Sep 13 18:05:07 GMT 2011 CHIP End BiasLSD Tue Sep 13 18:05:18 GMT 2011 CHIP Bias Tue Sep 13 18:06:03 GMT 2011 CHIP End Bias Tue Sep 13 18:06:10 GMT 2011 CHIP ReStart Patrol Tue Sep 13 18:13:29 GMT 2011 MKIV End Cal Tue Sep 13 18:13:35 GMT 2011 MKIV Start Patrol Tue Sep 13 18:53:31 GMT 2011 CHIP End Patrol Tue Sep 13 18:55:46 GMT 2011 MKIV End Patrol Tue Sep 13 18:55:56 GMT 2011 H-ALPHA End Patrol NOTE BY DARRYL: Tue Sep 13 19:34:33 GMT 2011 I stopped all instruments to do a CoMP Vacuum pumping, so I can position the Spar and pump. All RA and Dec drive turned off. end COMP COMMENT BY DARRYL: Tue Sep 13 19:35:59 GMT 2011 Pumping down the vacuum now, so far all seems to work OK. I'm doing this during the day rather than overnight because I'm unfamiliar with the process and I want to do it correctly and safely. end Tue Sep 13 19:57:04 GMT 2011: PSPT Start Patrol NOTE BY DARRYL: Tue Sep 13 21:47:32 GMT 2011 Had a power outage up here from about 2030 to 2130 UT. Recovering now. end

```
**PSPT PROBLEM COMMENT BY DARRYL**: Tue Sep 13 22:42:50 GMT 2011
Some kind of Com port problem, Sparc can't communicate with PC.
  end
COMP COMMENT BY DARRYL: Wed Sep 14 03:09:39 GMT 2011
Vacuum is pumped down to 2E-6 torr, all went well. Can be filled and used
tomorrow, didn't fill it tonight because we only have a little LN2 left
but we'll get a delivery tomorrow.
____end___
**PSPT PROBLEM COMMENT BY DARRYL**: Wed Sep 14 03:11:43 GMT 2011
PC has some kind of communication problem, I emailed info about it.
____end_
Wed Sep 14 03:21:11 GMT 2011
        MkIV
17_35.rawmk4
              17_50.rawmk4
                              18 16.rawmk4
                                             18_35.rawmk4
                                                            18_49.rawmk4
17 38.rawmk4
              17 57.rawmk4
                              18 19.rawmk4
                                             18 37.rawmk4
                                                            18 52.rawmk4
17_41.rawmk4
              18 03.rawmk4
                              18 25.rawmk4
                                             18 40.rawmk4
                                                            c17 54.rawmk4
17_44.rawmk4
              18 10.rawmk4
                              18 29.rawmk4
                                             18 43.rawmk4
                                                            c18 00.rawmk4
17 47.rawmk4
              18 13.rawmk4
                              18 32.rawmk4
                                             18 46.rawmk4
                                                            c18 07.rawmk4
```