
Mauna Loa Solar Observatory Observer's Log

Thu Jun 28 16:22:26 GMT 2012

Year: 12 Doy: 180

Observer: berkey

Thu Jun 28 16:31:20 GMT 2012 H-ALPHA Start Patrol

Thu Jun 28 16:29:51 GMT 2012 CHIP Start Patrol

Thu Jun 28 16:39:58 GMT 2012 COMP Start Patrol

Thu Jun 28 16:39:48 GMT 2012: PSPT Start Patrol

Thu Jun 28 16:57:50 GMT 2012: PSPT Abort Patrol

Thu Jun 28 17:04:57 GMT 2012: PSPT Start Patrol

WEATHER COMMENT: Thu Jun 28 17:05:14 GMT 2012

clear skies, wind 25mph from the S, temp 42F

____end____

CHIP PROBLEM COMMENT BY BEN: Thu Jun 28 17:33:20 GMT 2012

For some reason the video signal for alakai is blank. Chip seems to be functional so no reboot for now.

____end____

Thu Jun 28 17:45:39 GMT 2012 MKIV End Patrol

Thu Jun 28 17:45:45 GMT 2012 MKIV Start Cal

Thu Jun 28 18:04:29 GMT 2012 MKIV End Cal

Thu Jun 28 18:02:47 GMT 2012 CHIP LSD

Thu Jun 28 18:04:32 GMT 2012 CHIP End LSD

Thu Jun 28 18:04:41 GMT 2012 CHIP BiasLSD

Thu Jun 28 18:05:28 GMT 2012 CHIP End BiasLSD

Thu Jun 28 18:05:36 GMT 2012 CHIP Bias

Thu Jun 28 18:09:13 GMT 2012: PSPT Abort Patrol

Thu Jun 28 18:06:18 GMT 2012 CHIP End Bias

Thu Jun 28 18:06:27 GMT 2012 CHIP ReStart Patrol

Thu Jun 28 18:10:10 GMT 2012 COMP End Patrol

NOTE BY BEN: Thu Jun 28 18:09:42 GMT 2012

Fast fog blew in from the south, domes are closed I am pretty sure we didnt get any water on the telescopes

____end____

Thu Jun 28 18:11:52 GMT 2012 H-ALPHA End Patrol

Thu Jun 28 18:12:39 GMT 2012 CHIP End Patrol

CHIP COMMENT BY BEN: Thu Jun 28 18:16:47 GMT 2012

rebooting alakai

____end____

CHIP COMMENT BY BEN: Thu Jun 28 18:59:15 GMT 2012

Looks like the alakai monitor died

____end____

NOTE BY BEN: Thu Jun 28 21:05:18 GMT 2012

Still light rain.

____end____

NOTE BY BEN: Thu Jun 28 21:13:59 GMT 2012

Removed /olddata and the tape drive from kenobi

____end____

NOTE BY BEN: Fri Jun 29 00:17:13 GMT 2012

changed the power distribution system for the console. No more power strips plugged into other power strips. Consolidated things into groups and was able to remove a few extra power strips.

While doing this chip, ulua and the network devices had to be powercycled but everything looks to have come back properly.

___end___

NOTE BY BEN: Fri Jun 29 00:18:44 GMT 2012

also powercycled kenobi

___end___

Fri Jun 29 00:21:03 GMT 2012

MkIV

16_57.rawmk4	17_12.rawmk4	17_27.rawmk4	17_42.rawmk4	c17_51.rawmk4
17_01.rawmk4	17_15.rawmk4	17_30.rawmk4	17_48.rawmk4	c17_58.rawmk4
17_04.rawmk4	17_18.rawmk4	17_33.rawmk4	17_54.rawmk4	
17_06.rawmk4	17_21.rawmk4	17_36.rawmk4	18_01.rawmk4	
17_09.rawmk4	17_24.rawmk4	17_39.rawmk4	c17_45.rawmk4	