

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Wed Feb 10 16:47:03 GMT 2016

Year: 16 Doy: 041

Observer: waters

WEATHER COMMENT: waters: Wed Feb 10 17:14:13 GMT 2016

Temp 37F with windspeed at about 5mph from the West-Southwest. Clear sky at present.

\_\_\_\_end\_\_\_\_

Wed Feb 10 18:03:49 GMT 2016 KCOR Start Synoptic Patrol

GENERAL OBSERVATORY COMMENT BY waters: Wed Feb 10 18:39:16 GMT 2016

Contractors are up and working leveling the bottom of the concrete form they made.

\_\_\_\_end\_\_\_\_

Wed Feb 10 19:18:02 GMT 2016 KCOR End Patrol

Wed Feb 10 19:18:03 GMT 2016 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20150323.ini

Wed Feb 10 19:35:09 GMT 2016 KCOR End Calibration Script

Wed Feb 10 19:35:26 GMT 2016 KCOR Start Synoptic Patrol

Wed Feb 10 19:35:26 GMT 2016 KCOR Start Synoptic Patrol

GENERAL OBSERVATORY COMMENT BY waters: Wed Feb 10 19:36:17 GMT 2016

SGS adjusted

\_\_\_\_end\_\_\_\_

GENERAL OBSERVATORY COMMENT BY waters: Wed Feb 10 21:41:16 GMT 2016

Disconnected and moved the camera's that were on the deck inside. Taped any cords that couldn't be moved to the wall next to the door. The North cam is in the box Hale came in to give it support and the other is on the side. Blocks are in front of the box next to the UPS'. Concrete has been set and is drying. Should be good to walk on tomorrow, just mind the step up. SGS adjusted.

\_\_\_\_end\_\_\_\_

GENERAL OBSERVATORY COMMENT BY waters: Wed Feb 10 23:48:07 GMT 2016

SGS adjusted. The plug that is outside on the deck keeps tripping. Tried to use it and wouldn't work. Noticed that when we tested it, the light wouldn't stay on and we had to keep resetting it everytime. Not sure what happened to it.

\_\_\_\_end\_\_\_\_

GENERAL OBSERVATORY COMMENT BY waters: Thu Feb 11 02:17:20 GMT 2016

Sky is getting a bit bright. Not too bad yet, will keep an eye on it..

\_\_\_\_end\_\_\_\_

Thu Feb 11 02:22:19 GMT 2016 KCOR End Patrol