Mauna Loa Solar Observatory Observer's Log \_\_\_\_\_ Wed Sep 14 16:51:03 GMT 2016 Year: 16 Doy: 258 Observer: berkey WEATHER COMMENT: berkey: Wed Sep 14 16:51:07 GMT 2016 Temp: 43.2f, Humidity: 81%, Pressure: 28.649in, Wind: 9mph from 265degs, Skies: clear end Wed Sep 14 17:14:59 GMT 2016 COMP Start Patrol on cookbook: HOP316.cbk Wed Sep 14 17:24:04 GMT 2016 KCOR Start Synoptic Patrol Wed Sep 14 18:03:54 GMT 2016 CoMP Paused for clouds Wed Sep 14 18:04:00 GMT 2016 KCOR End Patrol GENERAL COMMENT BY berkey: Wed Sep 14 18:04:55 GMT 2016 Clouds coming over the mountain from the SW. Pausing instruments end Wed Sep 14 18:19:04 GMT 2016 CoMP Restarted from pause Wed Sep 14 18:26:37 GMT 2016 CoMP Paused for clouds Wed Sep 14 18:30:03 GMT 2016 CoMP Restarted from pause Wed Sep 14 18:41:47 GMT 2016 CoMP Paused for clouds GENERAL COMMENT BY berkey: Wed Sep 14 18:53:10 GMT 2016 Closing the dome for now end GENERAL COMMENT BY berkey: Thu Sep 15 00:08:11 GMT 2016 Hail, rain, fog, thunder blue skies all things happening at MLO right now. What fun. end Thu Sep 15 01:19:58 GMT 2016 CoMP Restarted from pause Thu Sep 15 01:19:58 GMT 2016 COMP End Patrol GENERAL COMMENT BY berkey: Thu Sep 15 02:55:41 GMT 2016 More power blips. end GENERAL OBSERVATORY COMMENT BY berkey: Thu Sep 15 05:01:17 GMT 2016 Forgot to log the Major task for this afternoon. Kcor and Comp occulting disks were swapped for the Fall.

\_\_\_\_\_

Kcor now has the 1009.6 disk installed. Comp is now using #31. For CoMP I changed the text value and saved the default ( so this should be robust with reboots). And the hwConfig.txt file in Kcor has been updated to reflect teh biggger disk.

While swapping the disks I took apart the Kcor field lens mount to try and check for pinched Orings or any other so of mis s-alignment. Near as I can tell it was Ok before the work and remains Ok. But it may be interesting to build some sort o f alignmet target for the field lens assembly to check it out on the bench. Perhaps this is as simple as a sheet of paper /plastic with alignent marks and annulus the side of of the occulter post that can be placed on the mount to give a better reference to check the alignment. For a better target we may require a 3d structure that rises to meet the top of the occulter post to better check centering.

\_\_\_\_end\_\_\_\_