Mauna Loa Solar Observatory Observer's Log .\_\_\_\_\_ Wed Mar 6 17:58:27 GMT 2019 Year: 19 Doy: 065 Observer: berkey WEATHER COMMENT: berkey: Wed Mar 06 18:01:55 GMT 2019 Temp: 40.2f, Humidity: 25%, Pressure: 28.673in, Wind: 3mph from 169degs, Skies: heavy overcast end KCOR COMMENT BY berkey: Wed Mar 06 18:02:38 GMT 2019 Testing changes the kcor header obsswid keyword end GENERAL COMMENT BY berkey: Wed Mar 06 18:02:39 GMT 2019 end Wed Mar 06 18:03:46 GMT 2019 Kcor Focus/alignment program exited Wed Mar 06 21:34:37 GMT 2019 Kcor Focus/alignment program exited KCOR COMMENT BY berkey: Wed Mar 06 22:01:15 GMT 2019 Bad T-cam removed from Kcor New t-cam 13889 installed and focused. Kcor observing code updated to support 2 cameras again and the kcorconfig.ini file has be updated to point to 13889. With a quick test on a overcast sky; all systems seem to be go. end

GENERAL COMMENT BY berkey: Thu Mar 07 01:16:47 GMT 2019

Replaced 3 of the kcor hepa vibration isolation pads becasue the rubbber was close to failure.

\_\_\_\_end\_\_\_

ONSITE STAFF: berkey