
Mauna Loa Solar Observatory Observer's Log

Sun Oct 2 17:22:07 GMT 2011

Year: 11 Doy: 275

Observer: koon

WEATHER COMMENT: Sun Oct 2 17:22:09 GMT 2011

Clear sky, wind=10 mph from the SSE, temp=50F.

____end____

Sun Oct 2 17:30:30 GMT 2011 MKIV Start Patrol

Sun Oct 02 17:30:22 GMT 2011 H-ALPHA Start Patrol

Sun Oct 2 17:30:59 GMT 2011 CHIP Start Patrol

Sun Oct 02 17:35:33 GMT 2011 COMP Start Patrol

Sun Oct 2 17:51:16 GMT 2011: PSPT Start Patrol

Sun Oct 2 18:01:40 GMT 2011 CHIP LSD

Sun Oct 2 18:03:12 GMT 2011 CHIP End LSD

Sun Oct 2 18:03:30 GMT 2011 CHIP BiasLSD

Sun Oct 2 18:04:20 GMT 2011 CHIP End BiasLSD

Sun Oct 2 18:04:28 GMT 2011 CHIP Bias

Sun Oct 2 18:05:05 GMT 2011 CHIP End Bias

Sun Oct 2 18:05:12 GMT 2011 CHIP ReStart Patrol

PSPT PROBLEM COMMENT BY DARRYL: Sun Oct 2 18:21:46 GMT 2011

Crashed, restarted. The "ftr home" command was running on the PC and not stopping, and I could hear a tone coming from the instrument, after doing a "KillPspt" I pressed the Enter button on the PC to stop the "ftr home" command and then I ran "Daily Obs" to continue, so far it seems to be doing well.

____end____

Sun Oct 2 18:22:08 GMT 2011: PSPT Start Patrol

Sun Oct 2 18:25:01 GMT 2011: PSPT Start Patrol

WEATHER COMMENT: Sun Oct 2 19:30:48 GMT 2011

Cirrostratus has moved in, pausing coronal instruments.

____end____

Sun Oct 02 19:32:45 GMT 2011 COMP End Patrol

Sun Oct 2 19:35:02 GMT 2011 MKIV End Patrol

****EVENT COMMENT BY DARRYL****: Sun Oct 2 19:37:42 GMT 2011

Lots of flaring in the NW active regions.

____end____

NOTE BY DARRYL: Sun Oct 2 19:43:00 GMT 2011

Tried gluing the guider telescope cover with silicone sealer this time.

____end____

NOTE BY DARRYL: Sun Oct 2 20:37:50 GMT 2011

Adjusted main dome slot.

____end____

GONG COMMENT BY DARRYL: Sun Oct 2 22:06:35 GMT 2011

I put the shipment of spare HDD in the GONG shelter, on floor next to blue cabinet on optical bench side.

____end____

Sun Oct 2 23:02:42 GMT 2011 CHIP LSD

Sun Oct 2 23:04:09 GMT 2011 CHIP End LSD

Sun Oct 2 23:04:19 GMT 2011 CHIP BiasLSD

Sun Oct 2 23:04:53 GMT 2011 CHIP End BiasLSD

Sun Oct 2 23:05:01 GMT 2011 CHIP Bias

Sun Oct 2 23:05:25 GMT 2011 CHIP End Bias

Sun Oct 2 23:05:34 GMT 2011 CHIP ReStart Patrol

PSPT PROBLEM COMMENT BY DARRYL: Sun Oct 2 23:37:22 GMT 2011

I fixed the dome rotator control box that was reported as partially pulled off the wall, I added a better wall anchor.

____end____

Sun Oct 2 23:59:48 GMT 2011: PSPT Start Patrol

Mon Oct 3 00:17:48 GMT 2011 CHIP End Patrol

WEATHER COMMENT: Mon Oct 3 00:17:53 GMT 2011

Clouds too thick for spar tracking, shutting down instruments.

____end____

Mon Oct 3 00:18:34 GMT 2011: PSPT Abort Patrol

Mon Oct 03 00:20:17 GMT 2011 H-ALPHA End Patrol

Mon Oct 3 01:11:51 GMT 2011

MkIV

17_30.rawmk4	17_57.rawmk4	18_23.rawmk4	18_49.rawmk4	19_20.rawmk4
17_33.rawmk4	17_59.rawmk4	18_26.rawmk4	18_52.rawmk4	19_23.rawmk4
17_36.rawmk4	18_02.rawmk4	18_29.rawmk4	18_55.rawmk4	19_25.rawmk4
17_39.rawmk4	18_05.rawmk4	18_32.rawmk4	18_58.rawmk4	19_28.rawmk4
17_42.rawmk4	18_08.rawmk4	18_35.rawmk4	19_01.rawmk4	19_31.rawmk4
17_45.rawmk4	18_11.rawmk4	18_38.rawmk4	19_04.rawmk4	
17_48.rawmk4	18_14.rawmk4	18_41.rawmk4	19_10.rawmk4	
17_51.rawmk4	18_17.rawmk4	18_44.rawmk4	19_14.rawmk4	
17_54.rawmk4	18_20.rawmk4	18_46.rawmk4	19_17.rawmk4	