
Mauna Loa Solar Observatory Observer's Log

Fri Jul 24 16:28:50 GMT 2015

Year: 15 Doy: 205

Observer: stueben

WEATHER COMMENT: stueben: Fri Jul 24 16:29:01 GMT 2015

Clear, light southeastern breeze, temp 47F.

____end____

Fri Jul 24 16:47:01 GMT 2015 COMP Start Patrol

Fri Jul 24 17:00:15 GMT 2015 KCOR Start Synoptic Patrol

Fri Jul 24 17:58:19 GMT 2015 KCOR End Patrol

Fri Jul 24 17:58:20 GMT 2015 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20150323.ini

Fri Jul 24 18:15:37 GMT 2015 KCOR End Calibration Script

Fri Jul 24 18:15:54 GMT 2015 KCOR Start Synoptic Patrol

Fri Jul 24 18:15:55 GMT 2015 KCOR Start Synoptic Patrol

Fri Jul 24 20:41:23 GMT 2015 COMP End Patrol

Fri Jul 24 20:51:18 GMT 2015 COMP Start Patrol

GENERAL OBSERVATORY COMMENT BY stueben: Fri Jul 24 20:52:24 GMT 2015

Reconfigured dome shutter and adjusted sgs offsets.

____end____

Fri Jul 24 21:08:50 GMT 2015 KCOR End Patrol

Fri Jul 24 21:09:20 GMT 2015 CoMP Paused for clouds

Fri Jul 24 21:10:15 GMT 2015 CoMP Restarted from pause

Fri Jul 24 21:12:04 GMT 2015 COMP End Patrol

WEATHER COMMENT: stueben: Fri Jul 24 21:13:25 GMT 2015

In orographic clouds, instruments idled.

____end____

PSPT PROBLEM COMMENT BY stueben : Fri Jul 24 23:38:28 GMT 2015

Powered up pspt with the new cables - no smoke, bangs or bright flashes of light. I entered a few simple commands from the pc, all worked. I then started pspt program on the sun and tried a normal startup, which worked up until it tries to take the 3 dark frames where the program then hangs. So the new cables don't seem to have fixed the problem of not getting data back from the camera.

____end____