
Mauna Loa Solar Observatory Observer's Log

Tue Jun 02 21:45:49 GMT 2026

Year:26 Doy:153

Observer: berkey

Weather COMMENT BY berkey: Tue Jun 02 21:47:11 GMT 2026

Heavy overcast and rain all morning. No expectation that it will clear.

____end____

UCOMP COMMENT BY berkey: Wed Jun 03 00:03:07 GMT 2026

ucomp realtime software and testing.

UCOMP2 Comptuer is online.

-Had to update the labview licenses, due to the new comptuer

-verified the ILX feed back to labview

-verified diffuser feedback and control

-verified ol feedback and control

-verified cover feedback and control

-verified basic camera connection. Currently camera0 is deteced as 10009 and camera1 is detected as 10006. This is backwards. We will need to swap cables at the comptuer.

Wrong config: RCAM to the left (south) TCAM to the right (north).

____end____

Weather COMMENT BY berkey: Wed Jun 03 00:03:24 GMT 2026

No data today.

____end____

GENERAL COMMENT BY berkey: Wed Jun 03 00:05:07 GMT 2026

Building maintenance

EPC on site for about 2 hours today. Limited work to build out the conduit to the panels, but heavy rain pervented significant progress.

____end____

Logger COMMENT BY berkey: Wed Jun 03 00:05:11 GMT 2026

Log closed

ONSITE STAFF: berkey

____end____