
Mauna Loa Solar Observatory Observer's Log

Sun Mar 3 17:26:51 GMT 2019

Year: 19 Doy: 062 Observer: rose

WEATHER COMMENT: rose: Sun Mar 03 17:33:01 GMT 2019

Temp: 37.2f, Humidity: 9%, Pressure: 28.828in, Wind: 9mph from 219degs, Skies: clear

end

KCOR PROBLEM COMMENT BY rose : Sun Mar 03 19:36:32 GMT 2019

camera broken no data today.

___end___

GENERAL COMMENT BY rose: Sun Mar 03 19:49:49 GMT 2019

Was measuring different parts of the upstairs to see how seeing responds to temperature. I am using an IR gun, but the laser is boken on it making difficult the measure the same spot on the dome every time. I notice as the dome warms the bott om of the dome is cooler than the top. I could not find an IR gun with a working laser. I cannot measure to same spot everytime so it is not very repeatable. I just found the button to turn on the laser. The IR gun is not borken. My measus ements were taken with the laser off. I am going to stop and go home because I am not feeling well today.

____end___

GENERAL COMMENT BY rose: Sun Mar 03 19:56:59 GMT 2019

spar		floor	loor dome east		dome west		dome south		dome north		wall east	wall west	wa
ll south		wall north											
normal	operati	ng open	windows										
fully	open shu	tters											
7:50		44.5	49.5	43.8	43.7	43.2	49.9	44.6	44	44.7			
8:00	44.3	46.3	47	44.3	43.6	42.3	52.6	45.8	45.2	45.7			
8:10	45.1	46.6		43	44.6	43	55.3	46.3	45.8	46.6			
8:20	45.5	47.3	49.5	45.2	45.3	45	57.1	47.1	46.4	47.2			
8:30	47.1	48.4	51.1	46	46.4	46.3	59	48.5	48	49			
8:40	48.3	49.6	51.5	46.7	47.8	47.1	59.6	49	48.5	49.4			
8:55	48.5	50.7	53.2	49.8	49.4	49.5	61.5	50.5	49.6	51.4			
9:05	52.5	52	54.5	48	51.6	50.3	63.2	52.1	51.5	52.8			
9:15	54.6	53.2	56.3	49.6	52.2	51.9	63.9	53.2	52.4	53.8			
9:25	55.2	54.6	55.5	51	52.5	51.4	64.8	53.5	53	54.8			

excel spreadsheet on desktop

___end___

ONSITE STAFF: rose